

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13228

Date In: 17 FEB 26 Author: MGRAY  
Promised Date: 31 DEC 26 Stock No: 11227  
: Year: 2025  
Customer Name: 15106 - FEUERSTEIN, MA Manufacturer: GRAND DESIGN  
Address: 313 VENUS WAY Brand: IMAGINE XLS  
: MADISON, WI Model: 23LDE  
Postal/Zip: 53718 Miles/Hrs: 0  
Phone#(res): 608-577-7485 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: MJ.FEUERSTEIN@SBCGLOBA Tag#: db 2/23  
Purchased Date: 16 APR 25 :  
Delivery Date: 08 MAY 25 :  
InService Date: :  
Serial#: 573TE282XS3440902 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: BEARING REPACK - CMR REQUESTS THAT THEY E 15106 FEUER  
ARE JUST DONE AS THEY ARE TAKING ON A  
LONG TRIP.  
CAUSE: repack all 4 bearings  
CORRECTION: removal of tires and hubs from axles i  
also inspected bearings ok repack  
bearings with new grease and hub seals  
installed all 4 hubs and torqued tires  
to spec  
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF I PD GOODW  
REPAIR IS NEEDED.  
CAUSE: roof inspection  
CORRECTION: roof inspection was done all vents and  
sealants are ok  
WARR COMPLAINT: WARRANTY REPAIR 1 - FENDER SKIRTS HAVE W 1020 GRAND  
SOME CRACKING. LOOK LIKE THEY HAVE been  
tightened down to tight.  
CAUSE: pics and measurements taken on door side  
fender skirt is cracked  
CORRECTION: remove the damage fender skirt on door  
side re attached new fender skirt and  
silicone the edges of fender skirts  
2 COMPLAINT: THE NEWLY INSTALLED SHADE HAS CAPS ON W 1020 GRAND  
THE BOTTOM SECTION TO KEEP METALL INSIDE  
AND NONE OF THE OTEHR SHADES DO, ARE  
THEY SUPPOSED TO BE CAPPED OLIKE THAT?  
AND IF SO CAN WE GET THE CAPS TO REPLACE  
THEM?

Continued on page 2

Work Order : 13228

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      inspection of all shades the newly shade
                  that was installed the aluminum flap rod
                  that in in was cut to exact size so you
                  can installed cap but all other shade
                  the aluminum flap rods are cut short
                  intentionally so you cant install caps
                  ot get cut.  unless the manufacturer can
                  send us aluminum fat rods and end caps
                  we can cut to size measurements and pics
                  taken 4/1 wrong parts recieved
      CORRECTION: inspection of all shades will need 3 new
                  shades with end caps ....  ... put parts
                  into the unit for the cusotmer
    
```

```

*****
Job # Part No      Description           PARTS      Bill to      Qty      Price      Total
*****
1      030999740786 2pk TEKONSHA GREASE SEAL E-15106      2      12.18      24.36
WARR0 822070396      TRIM ABS TANDEM FENDER S W-1020      1      48.04      48.04
2      82204511      SHADE END CAPS ONLY BLAC W-1020      3      2.11      6.33
2      82201797      SHADE END CAP / BLK OVAL W-1020      6      0.92      5.52
    
```

```

*****
Job#  Lab Code  Description           LABOUR      Mech Bill to      Hrs      Rate      Total
*****
  1  R735      BEARINGS, PACK (TANDEM JS E-15106      1.14      130.00      148.20
  RI  Z991      PREFORM ROOF INSPECTIO JS I-PD      0.30      70.00      21.00
ARR01 Z992      MISC LABOUR CODE (WARR JS W-1020      0.50      140.00      70.00
  2  Z992      MISC LABOUR CODE (WARR JS W-1020      0.50      140.00      70.00
  1  R735      BEARINGS, PACK (TANDEM JS E-15106      1.60      130.00      208.00
  1  R735      BEARINGS, PACK (TANDEM JS E-15106      0.26      130.00      33.80
ARR01 RV30L-2  FENDERSKIRT R&R TANDEM JS W-1020      1.00      140.00      140.00
  2  WARR      MANUFACTURER WARRANTY JGK W-1020      0.50      140.00      70.00
  2  WARR      MANUFACTURER WARRANTY JGK W-1020      0.00      140.00      0.00
    
```

```

*****
Job #  Excode  Description           EXTRAS      bill to      Qty      Price      Total
*****
  1  SSE      SHOP SUPPLIES - EXTERNAL E-15106      1.00      29.25      29.25
  2  FRT      FREIGHT              W-1020      1.00      16.74      16.74
  2  FRT      FREIGHT              W-1020      1.00      17.46      17.46
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      15106      24.36      390.00      0.00      29.25      24.43      468.04
I      PD      0.00      21.00      0.00      0.00      0.00      21.00
W      1020      59.89      350.00      0.00      34.20      0.00      444.09
    
```

Continued on page 3

Work Order : 13228

\*\*\*\*\*

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	84.25	761.00	0.00	63.45	24.43	933.13

&k2S  
&k0S