

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 64674
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50162 - TELESIA A. WADSWORTH
Address: 100 JACK CT ODON, IN

47562

Phone: 812-636-5211

Stock Number: 10681 - 2021 CATALINA 293QBCKLE 5ZT2CAUB5MX021147

VIN: 5ZT2CAUB5MX021147 HIN: SER#: 5ZT2CAUB5MX021147

Mileage: 0 Work Order Comp: 31 AUG 21

Auth. No: Dealer #:

Warr. Date: 27 MAR 21 Work Order Date: 10 JUL 21 Inv #: 370619

WO # Job # Description JOB INFORMATION

64674 6 The bottom drawer by the kitchen sink opens when going down the road

THE BOTTOM DRAWER BY THE KITCHEN SINK OPENS WHEN GOING DOWN THE ROAD.

Checked bottom drawer under kitchen sink. Stops at rear of slide is bent and will not keep drawer closed in transit. Slides need replaced. 7/13/2021: Turned in parts request for a new set of drawer slides.

64674 2 KITCHEN SINK YOU NEED TO FILL THE SINK TO ABOUT 3-4 INS AND THEN DRAIN IT IT WILL LEAK WHEN IT IS DRAINING
KITCHEN SINK YOU NEED TO FILL THE SINK ABOUT 3-4 INCHES AND THEN DRAIN IT. IT WILL LEAK WHEN DRAINING.

Checked kitchen sink drain. Filled sink to 3-4 inches. Pulled drain stopper. Found a small drip above "P" trap. Removed complete drain from sink. Cleaned all parts. Reinstalled all drain parts. tightened all fittings securely. Filled sink three times and drained. No leaks or drips at thius time.

64674 3 On the entry door where the steps fold in the metal is bent where the blue tape is
ON THE ENTRY DOOR WHER THE STEPS FOLD IN THE METAL IS BENT WHERE THE BLUE TPE IS.

Checked entrance door flange. Flange is bent on both sides. Straightened both flanges. Adjusted latches so they don't rub side flanges when opening and closing.

Claim : 64674

 WO # Job # Description JOB INFORMATION

64674 4 THE SLIDE ROOM THE FRONT END OF THE SLIDE THE PANEL ABOUT HALF
 WAY DOWN IS COMING LOOSE
 THE SLIDE ROOM THE FRONT END OF THE SLIDE THE PANEL ABOUT HALFWAY
 DOWN IS COMING LOOSE.
 Checked trim on living room slideout. Wall panel on end has come
 loose. Reattached wall panel wih small staples. Filled all
 holes with matching putty.

64674 5 THE PANEL BY THE BATHROOM DOOR YOU CAN SEE THE NAILS need to
 install seam tape
 THE PANEL BY THE BATHROOM DOOR YOU CAN SEE THE NAILS. NEED TO
 INSTALL SEAM TAPE.
 Checked curved panel next to bathroom door. Small staples
 sticking out. Counter sunk staples. Found some matching seam
 tape to cover staples. Applied seam tape from ceiling to floor.

Part No	Job#	Description	PARTS	Qty	Price	Total
C01230004	6	DRAWER SLIDE, BALL		2.00	1.87	3.74
C01230005	6	DRAWER SLIDE, BALL		2.00	0.52	1.04

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	130.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.50	130.00	65.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	130.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		1.00	130.00	130.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.50	130.00	65.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.50	130.00	65.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.50	130.00	65.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	6	UPS-CABINET PARTS		1.00	15.47	15.47

Parts Total: 4.78
 Labour Total: 390.00
 Sublet Total: 0.00
 Extras Total: 15.47

>>>> Claim Total: 410.25

Customer Signature: _____

Date: _____