



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27162



WO #: 27162 (Appointment Date: 14 MAY 2026 - Time: 02:30pm)

Customer: 93143 - POPE, GREGORY
Address: 1144 ELIZABETHTON HWY
BLUFF CITY, TN
37618

Home Phone: 423-534-0403

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11017

Stock Desc: 2025 C FOREST RIVER FORESTER
3251DSLEF

Model: 3251DSLEF

Serial #: 1FDXE4FN0SDD26625

Chassis #: 1FDXE4FN0SDD26625

Mileage: 12121

Key #: 5299

Req'n #:

License #:

Trim:

Purchase Date: 12 AUG 25

Date In: 14 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 12 AUG 25

Job #3 - Warranty

COMPLAINT: WH is leaking at pop off check and advise

CORRECTION: TECHS VERIFIED THERE IS NO ISSUE AT THIS TIME, NO LEAK FOUND

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CABINET DOOR ABOVE DINNETE ON RIGHT IS PEELING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR
REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR
LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CABINET DOOR ABOVE DINNETE ON LEFT IS PEELING

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR
REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR
LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CABINET DOOR TO LEFT OF BATHROOM MIRROR IS PEELING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR
REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR
LABOR .50

Customer #: 93143
POPE, GREGORY



Subtotal for Job #6: 0.00

W/O: 27162

Job #7 - Warranty

COMPLAINT: WINDOW BEHIND FRONT SLIDE IS LEAKING CAUSING THE BLIND TO DISCOLOR

CAUSE: SKYLIGHT IS CRACKED AND ALLOWING WATER TO LEAK INTO THE UNIT. THIS HAS DAMAGED THE INTERIOR WALL PANEL, SHADE AND BATTON.

CORRECTION: REMOVE SKYLIGHT, CLEAN AREA, REPLACE WITH NEW SKYLIGHT AND RESEAL AREA.

REMOVE AND REINSTALL WINDOW. REMOVE DAMAGED WALL PANEL AND BATTON, REPLACE WITH NEW. WILL NEED TO REMOVE AND REINSTALL THE CABINETS ON WALL, COUNTER TOP, KITCHEN FAUCET TO ACCESS THE DAMAED WALL PANEL.

WILL ALSO NEED TO REPLACE THE WINDOW SHADE AND VALANCE DUE TO WATER DAMAGE. LABOR 10.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CABINET DOOR ABOVE ENTRY DOOR IS LEAKING CHECK AND ADVISE

CAUSE: OVERLAY IS PEELING OFF CABINET DOOR

CORRECTION: REPLACE CABINET DOOR
REMOVE CABINET DOOR, REMOVE HARDWARE TO INSTALL ON NEW CABINET DOOR
LABOR .50

Subtotal for Job #8: 0.00

Customer Order

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00



Customer #: 93143
POPE, GREGORY

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 21 May 2026

Customer Signature : _____

