



Warranty Claim Form

Date: 5/22/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2620T3445367

Imagine 22MLE

Retail Purchase Date: null

Work Started: 12/8/2025

Work Completed: 12/8/2025

Claim Status: Paid

Dealer Work Order #: 13157B

Unit Offline Date: 11/4/2025

Claim #: 967717

Labor: \$112.00

Parts: \$0.00

Shipping: \$0.00

Total: \$112.00

Notes: Approved by upper management. 5/7 DW JPH 2-9-26 810112 will this solve the problem?

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: Loose trim above the sofa.

Hours: .1

Cause: Loose trim from manufacturer.

Amount: 14.00

Remedy: Used a pin nailer to secure then set the nails and puttied them.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 810112 AWNING - Awning Fabric Repair *Fault Code:* Damaged/Maintenance Only

Problem: Water is getting through the seam of the awning fabric where it is stitched.

Hours: .2

Cause: Water leaking through seam.

Amount: 28.00

Remedy: Used crayon and rubbed over the seam.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

Operation Line # 3

Flat Rate Code: 720124 Range/Oven - Range/Oven Front Panel *Fault Code:* Improper Installation/Build Module

Problem: The stove edge has a few scratches.

Hours: .3

Cause: Scratched from manufacturer.

Amount: 42.00

Remedy: Used a brillo pad to remove the slight scratches then polished the edges.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

Operation Line # 4

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Damaged/Maintenance

Problem: Ceiling trim has black marks on them.

Hours: .2

Cause: Black marks on white plastic ceiling trim.

Amount: 28.00

Remedy: Used quick solve and a cloth to remove black marks on all of the ceiling trim.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: