



RECREATIONAL VEHICLES

Claim CLAIM4432 (KZ0041437)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre- auth Dealer	Repairing dealer name	Changed			Date of Purchase
							Labor rate	warranty rate	Type	
CLAIM4432 (KZ0041437)	27172	5/16/2026	1/1/0001	4EZTL2320S4046550	CUST-002602	TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Standard	4/28/2026

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6641_03_A	Repair Jiffy Sofa - Improperly Installed - Repair/adjust/tighten	0.4	0.2	35	0	1	0	Approved
	Complaint	Left side of sofa section, foot rest hitting bottom brace							
	Cause	Bottom brace is too close to the base							
	Correction	Need to add washer to raise off the base							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6639_01_B	R/R Jiffy Sofa, Front - Damaged - Replace	0.5	0.6	105	0	1	0.2	Approved
	Complaint	Left side of sofa section massage was not working, tech found wires were disconnected. After connecting these wires, the massage works, however the cup holder light will not turn off now							
	Cause	Wiring issues on left side of sofa section seating							
	Correction	Replace seating on left side of sofa							

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	157.50	Approved labor & subLet	140.00
Submitted freight	0.00	Approved freight	0.00
Total Submitted	<u>157.50</u>	Total approved	<u>140.00</u>