

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12820

Date In: 25 SEP 25 Author: KOTT
Promised Date: 31 DEC 26 Stock No: 11253
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA TT
: WISCONSIN RAPIDS, WI Model: 32BHQ5
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 12/1** NO CHARGE P
Purchased Date: 14 MAR 26 :
Delivery Date: 04 MAY 26 :
InService Date: :
Serial#: 4X4TPUH28SP103645 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: FOUND WHILE WINTERIZING THE LOT- DS W 1021 FORES
FENDERSKIRT IS CRACKED
CAUSE: 1016 DAMAGED Skirting cracked. I
removed the old skirting and installed
the new skirting.
CORRECTION: Done
2 COMPLAINT: FOUND WHILE WINTERIZING THE LOT- THE W 1021 FORES
THERMOSTAT IS COMING OFF OF THE WALL
CAUSE: Did more testing with the thermostat
falling out of the wall put in new
thermostat still does not work did
testing with Joe to find out that the
control board is bad. We need a
thermostat and a control board that
matches. The t-stat wasnt compatible
with the control board. I hooked the
new board and t stat and and it would
flash an FC code which is a
communication issue. GE doesn't have
helpful information anywhere and the
t-stat is labeled A,B and C on the back
amd none of the wires are labeled A,B
and C. The information i did find got me
close and everything is hooked up
correctly. I hooked the t-stat up
directly to the contro board to see if
its a wiring issue and the same issue is
happening. Upon further digging we found

Continued on page 2

Work Order : 12820

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                out this isn't the right t stat and we
                                took one off the lot that was the right
                                model and it works. I put the a/c back
                                together and ran the a/c.
CORRECTION: New control bar and thermostat Done
3 COMPLAINT: Living room ac not working           W      1021   FORES
CAUSE:      5/13 we need a control board too. Anna
            is looking into it
CORRECTION: ... INSTALLED THE CONTROL BOARD AND THE
            THERMOSTAT- ALL CHECKS GOOD
    
```

```

*****
Job # Part No Description           PARTS           Bill to Qty Price Total
*****
2      82205773 GE THERMOSTAT / HAIER REC. W-1021 1 46.87 46.87
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 WARR MANUFACTURER WARRANTY JGK W-1021 0.49 140.00 68.60
1 WARR MANUFACTURER WARRANTY JL W-1021 0.01 140.00 1.40
1 RV30L-2 FENDERSKIRT R&R TANDEM JGK W-1021 1.00 140.00 140.00
2 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
2 WARR MANUFACTURER WARRANTY JL W-1021 0.02 140.00 2.80
2 F930 THERMOSTAT, R & R JGK W-1021 0.48 140.00 67.20
2 F930 THERMOSTAT, R & R JL W-1021 0.02 140.00 2.80
3 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 140.00 70.00
2 WARR MANUFACTURER WARRANTY JGK W-1021 0.48 140.00 67.20
2 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
    
```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
3 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
3 M MISCELLANEOUS NCP CONTROLL W-1021 0.00 0.00 0.00
3 M NCP FROM HAIER REC ADAPTER W-1021 0.00 9.40 0.00
3 M NCP THERMOSTAT FROM HAIER W-1021 0.00 12.12 0.00
    
```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 46.87 420.00 0.00 0.00 0.00 466.87
Totals 46.87 420.00 0.00 0.00 0.00 466.87
    
```

&k2S

Continued on page 3

Work Order : 12820

&k0S