



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72836-1  
 Promised Date:  
 no add 22

\*72836-1\*

WO #: 72836-1

Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date:  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9655 2026 TRACER 195RB  
 Serial#: 526825  
 Chassis#: 5ZT2TRJB8TB526825  
 Miles/Hrs:  
 Tag#:  
 Purchased Date:  
 Warranty Date:

Date In: 27 MAY 26  
 Time In:

**Job #01 - Warranty**

COMPLAINT: Pantry door leaning / WARRANTY ITEM

CAUSE: The pantry door is leaning due to improper insulation from factory. The door is approximately half an inch hitting the opposite side. Because of the improper installation the screws are hitting the frame on the opposite side and gouging the plastic and metal frame.

CORRECTION: Pantry door jam is leaning due to improper insulation at factory. Prior to removing the pantry door, the TV needs to be unwired, unscrewed and removed. The Inn of flame fireplace has to be unwired, unscrewed and removed from the factory location. The entry door has to be unscrewed removed from the factory location in place in a safe place. I then have to inspect the framing that holds up the door. Once inspected to make sure that I do not have to rebuild the framing of the wall the door jams I can then replace the door. Pantry door jam needs to be ordered due to the damage of the door framing needs to be replaced. Pantry door jam old pantry door jam needs to be unscrewed and replaced. The new pantry door jam needs to be screwed back into factory location. The pantry door framing needs to be ordered. The old pantry door frame needs to be taken off unscrewed and replaced to the scratches the new pantry door frame needs to be ordered screw back in and replaced back to factory location. The door with all the new parts that needs to be replaced back to factory location TV back to installed screwed back in the inflame needs to be screwed back into factory location. The door needs to be replace placed back into factory location and adjusted.

Photos attached  
 Request 4 hours

**Labor**

Job #	Description	Total
01	Pantry door leaning MISC LABOUR CODE (WARRANTY)	N/C
<b>Subtotal for Job #01:</b>		<b>0.00</b>

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,

\*1000\*

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 27 May 2026

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 72836-1  
Promised Date: 08 APR 26

\*72836-1\*

Customer #: 1000  
MYERS "RV" CENTER,  
INC.,

\*1000\*