



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79960
Promised Date:
21 MAY 26



CUSTOMER WORK ORDER

WO #: 79960

Customer: 56809 - COTTON, MICHAEL -
812-457-4757

Tag:

Author: BH

Location: 0527 CHECK PREAUTH

Stock #: 11714

Stock Desc: 2026 5W KEYSTONE

COUGAR SPORT 2700BH

Chassis #: 4YDFCGN29T2504783

Serial #: 4YDFCGN29T2504783

Mileage: 0

Licence:

Invoice #:

Date In: 18 MAY 26

Promised: 21 MAY 26

Date Sched:

Completed: 27 MAY 26

Warr. Date: 21 MAY 26

Job #SUPERLITE - Internal

COMPLAINT: INSTALL SUPERLITE HITCH

2010 & NEWER CHEVY REQUIRE ADDITIONAL BRACKET

CAUSE: GREG INSTALLED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
2600	2600 20K SUPERLITE SINGLE POINT 5W H	1.00	N/C	N/C
9582	ROTA-FLEX PIN BOX ISOLATOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SUPERLITE: 0.00

Job #1 - Internal

HAS TRADE HERE / DROPPING TRUCK OFF WED AM + WILL LEAVE HERE

Subtotal for Job #1: 0.00

Job #TURNOVER - Internal

INSTALL TURNOVER BALL GOOSENECK HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
GNRK1116	GNRK1116 TURNOVER BALL KIT	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #TURNOVER: 0.00

Customer #: 56809
COTTON, MICHAEL





Job #FPDINFW - Internal

COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS

CAUSE: New final

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Installed a new battery. Battery disconnect was broken i have a parts request in for a new one. Running lights and tail lights work properly brakes and Emergency Brakes work properly. Exterior inspection cap lights and hooked up lights work properly. Had to make a longer positive cable for the battery it was too short. Exterior inspection looks good roof inspection found a couple voids that I sealed with dicor self-leveling roof good now. Awning fabric and hardware looks and works properly Awning lights work properly Interior inspection put water in fresh tank and ran the water pump to flush out all the lines water pump works properly then hooked to city water to flush out all the lines water heater works properly on both. Stove works properly microwave works properly both ac units works properly furnace works properly refrigerator works properly. All the lights work properly all the windows and blinds work properly tv antenna works properly. Lp detector and smoke alarm works properly. Did my lp drop test on outside port with stove and furnace running made a small adjustment to the regulator.system has a leak when i held it 8 for 5 min. . Drained black tank and gray tank and left 1/3in the fresh tank for demonstration. Found the lp leak and got it fixed system works properly now. The lp doors the handles didn't match when locked so I made the handles match when locked. I got the battery disconnect replaced. Works properly

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050EHVP 30M-50F PIGTAIL	1.00	N/C	N/C
Subtotal for Job #FPDINFW:				0.00

Job #2 - Warranty

COMPLAINT: BATTERY DISCONNECT BROKE AND WILL NOT TURN

CAUSE: Battery disconnect broken

CORRECTION: I put in a parts request for a new one and i got it replaced and it works properly

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	95.00
Z990	MISCELLANEOUS REPAIR	JTW	0.00
Z990	MISCELLANEOUS REPAIR	JTW	95.00

Parts

Part #	Description	Qty	Price	Total
13268	Box - 12v Power Distribution - FW -	1.00	136.64	136.64

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BOX	1.00	12.62	12.62

Subtotal for Job #2: 339.26

Job #3 - Warranty

COMPLAINT: LP SYSTEM IS LEAKING. UNIT IS NOT PASSING MANOMETER TESTING.

CAUSE: Lp leak found during drop test

CORRECTION: So during my lp drop test I found that I had a leak when I was trying to hold 8 for 5min. So I sprayed all my connections and nothing showed up. So then I plugged off the line to the stove. No change.



Then the water heater not change then the furnace no change. I switched gauges no change. So then I had the only lp appliances capped off then I started spraying the connections again I finally found it the 90 degree elbow coming from the other tank. So I took it off cleaned the threads on both and applied pipe dope and tightened it up. Then I pressurize the system and gauge showed no leaks. So then I connected all my appliances spray checked them and no leaks. System is working properly

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	190.00

Subtotal for Job #3: 190.00

Job #7WAY - Internal

7WAY INSTALLED IN BED OF TRUCK

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #7WAY: 0.00

Customer Order

Parts Total:	136.64
Labour Total:	380.00
Sublet Total:	0.00
Extras Total:	12.62
WORK ORDER TOTAL:	529.26

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 May 2026

W/O: 79960
Promised Date: 21 MAY 26



Customer #: 56809
COTTON, MICHAEL

