

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12095B

Date In: 07 OCT 25 Author: KOTT
Promised Date: 31 MAY 26 Stock No: 11387
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: REFLECTION FW
: WISCONSIN RAPIDS, WI Model: 311BHS
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB: 11/18
Purchased Date: 07 APR 26 :
Delivery Date: 24 APR 26 :
InService Date: :
Serial#: 573FR3821S9929726 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - bunk door will not W 1020 GRAND
close
CAUSE: Mfg installed latch too high and the
center hinge was rubbing
CORRECTION: I removed screws from center hinge then
removed latch drilled out more material
reinstalled latch lower tested door
catches I then installed screws back
into center hinge door operates and
closes as it should now REQ. .50 HRS
WARR AUTH: .50
WARR COMPLAINT: WARRANTY REPAIR 2 - exterior kitchen W 1020 GRAND
paneling is separating
CAUSE: Loose paneling
CORRECTION: I used spray adhesive and sprayed the
back of panels then used a clamp to
secure i will let dry remove clamp and
it should be good REQ. .30 HRS WARR
AUTH: .20
WARR COMPLAINT: WARRANTY REPAIR 3 - The bedrooms ac fan W 1020 GRAND
is rubbing badly on the inner styrofoam
CAUSE: Mfg had the big fan misaligned it was
hitting sturofoam
CORRECTION: Removed the 10 screws and cover and
found the LG fan rubs on the styrofoam I
pushed fan over to right a hair tested
not rubbing i then reassembled
everything and tested again it now is

Continued on page 2

Work Order : 12095B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                making no sound and it runs properly PUC
                                OF MODEL AND SERIAL NUMBER ATTACHED REQ
                                .40 HRS  WARR AUTH: .30 HOURS
WARR    COMPLAINT:  WARRANTY REPAIR 4 - shade next to           W    1020    GRAND
                                dinette does not roll up
CAUSE:   The blind is too short and needs to be
                                re ordered  Shade inop Order new black
                                shade . Tag with info attached with pic
CORRECTION:  ... .. INSTALLED SHADE IN THE
                                UNIT- WHOEVER INSTALLED THE FIRST SHADE
                                INSTALLED IT WITH TO LONG OF SCREWS SO
                                HAD TO FIX THAT BEFORE THE INSTALL OF
                                THE BLIND
    
```

```

*****
Job # Part No Description      PARTS           Bill to  Qty   Price   Total
*****
WARR0 82201530 SHADE 50 X 38 BLACK MANUAL R W-1020      1    107.33   107.33
    
```

```

*****
Job# Lab Code Description      LABOUR    Mech Bill to      Hrs   Rate   Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.50  140.00   70.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.00  140.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.23  140.00   32.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.29  140.00   40.60
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.01  140.00    1.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020      0.50  140.00   70.00
ARR04 WARR      MANUFACTURER WARRANTY  JGK  W-1020      0.20  140.00   28.00
ARR04 WARR      MANUFACTURER WARRANTY  HOD  W-1020      1.00  140.00  140.00
    
```

```

*****
Job # Excode Description      EXTRAS           bill to  Qty   Price   Total
*****
ARR04 FRT      FREIGHT           W-1020      1.00   43.85   43.85
ARR04 FRT      FREIGHT           W-1020      1.00    0.00    0.00
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1020          107.33   382.20    0.00     43.85    0.00   533.38
                                Totals    107.33   382.20    0.00     43.85    0.00   533.38
    
```

&k2S
&k0S