



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27041



WO #: 27041 (Appointment Date: 22 APR 2026 - Time: 09:00am)

Customer: 93876 - RICKER, JERRY
Address: 670 BISHOP LOOP
GREENEVILLE, TN
37743

Home Phone: 864-979-3711

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #:
Stock Desc: 2024 FOREST RIVER FORESTER
Model:
Serial #: 1FDXE4FN9RDD42039
Chassis #:
Mileage: 3128
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 21 APR 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: DRIVER SIDE REAR COMPARTMENT DOOR IS ALLOWING WATER IN AROUND THE SEAL

CAUSE: TECH VERIFIED WATER IS LEAKING PAST THE SEAL DURING A WATER TEST

CORRECTION: REMOVE CURRENT SEALS, CLEAN AREA AND REPLACE WITH NEW
COMPARTMENT DOOR SEAL
LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: STATES THE MIDDLE ARE REAR COMPARTMENTS ARE LEAKING - BIG LONG
NARROW ONE

CAUSE: TECH VERIFIED WATER IS GETTING IN AROUND THE COMPARTMENT DOOR SEAL

CORRECTION: REMOVE THE CURRENT SEAL, CLEAN AREA AND REPLACE WITH NEW
COMPARTMENT DOOR SEAL THEN RETEST
LABOR .60

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ON THE FRONT ENTRY DOOR THE SCREWS ARE BACKING OUT AND LOOKS LIKE
THE FRAME IS COMING LOOSE FROM UNIT

CAUSE: VERIFIED THE LATCH SCREWS ON STRIKER SIDE IS LOOSE AND THE LATCH HOLDER
FOR THE SCREEN.

CORRECTION: NEED TO RESECURE SCREWS AND ADJUST THE SCREEN DOOR LATCH HOLDER
TO CORRECT CONCERN
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: WANTS MAGNET ON BATHROOM DOOR CHECKED, AND WANTS TO GO THRU
EVERYTHING ELSE SINCE ITS ALMOST OUT OF WAR.

CAUSE: MAGNET IS PULLING OUT OF THE DOOR AND MAGNET IS NOT WORKING AS DESIGNED

Customer #: 93876
RICKER, JERRY



CORRECTION: REMOVE FAULTY MAGNET, REPLACE WITH NEW MAGNET AND RELOCATE THE
MAGNET TO HOLD DOOR CORRECTLY
LABOR .50

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - External

PLEASE MEASURE FOR 2 RECLINERS AND GET PRICE. HE MAY WANT TO REPLACE COUCH WITH
2 RECLINERS

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 08 May 2026

W/O: 27041



Customer #: 93876
RICKER, JERRY

