



Warranty Claim Form

Date: 5/28/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FM3821TBB05690
Momentum 320G
Retail Purchase Date: null
Work Started: 5/1/2026
Work Completed: 5/18/2026

Claim Status: Paid
Dealer Work Order #: 13405B
Unit Offline Date: 4/21/2026

Claim #: 989143
Labor: \$98.00
Parts: \$4.90
Shipping: \$0.00
Total: \$102.90

Notes: TG 5-18-26 Dealer must complete the work within 6 months from the approval date and the job must be claimed within 45 days of the service completion date. If the work is not completed and claimed within this time frame, the approval is void and will be denied.

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: In the kitchen, left side corner trim has a crack and large gap in trim where they meet in corners. *Hours:* .1

Cause: Small crack from manufacturer in corner trim. *Amount:* 14.00

Remedy: Used putty to fill the crack and the upper corners on trim. *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	0.70

Operation Line # 2

Flat Rate Code: 560049 Lg. Comp./Pass Thru/Kitch./Ent. Ctr. - Adjust/ *Fault Code:* Improper Installation/Build
Repair Door (includes door and frame)

Problem: Bedroom door is peeling at the bottom. *Hours:* .2

Cause: Finish on door is chipped and peeling. *Amount:* 28.00

Remedy: Used wood marker to cover the bare areas on edge and bottom of the door. *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
-------------	--------------------	---------------------	------------	--------------	---------------

960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only	1	1	1.40
---	--	---	---	------

Operation Line # 3

Flat Rate Code: 560049 Lg. Comp./Pass Thru/Kitch./Ent. Ctr. - Adjust/ *Fault Code:* Improper Installation/Build
Repair Door (includes door and frame)

Problem: Rear bath door is peeling at the bottom. *Hours:* .2

Cause: Peeling finish on the bath door. *Amount:* 28.00

Remedy: Used wood marker to cover missing finish. *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.40

Operation Line # 4

Flat Rate Code: 690007 Shades - R&R Shade *Fault Code:* Improper Installation/Build

Problem: When bringing the bed down in the garage, the mattress tubbed against the valance and it's bent. *Hours:* .2

Cause: Manufacturer installed the valance so close to the bed lift, if the mattress is overhanging to one side this will keep happening. *Amount:* 28.00

Remedy: Used larger screws to reattach the valance and made sure the mattress is even on the platform. *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.40