

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 64969

Completed : 17 NOV 21 Customer : 50607 - DECLARATION OF LIV TR OF SA
Licence # : Invoice # :
Stock No : 10804 Description : 2021 5W KEYSTONE COUGAR HALF-TON 30
Tag : Date In : 09 AUG 21 Mileage : 0
Author : BJW Promised : 30 NOV 21
Location : 1117 CUSTOMER IS WA Date Sched :
Serial# : 4YDF30R22M2507298 Chassis# : 4YDF30R22M2507298
Warr. Date : 08 APR 21 Cust PO# :
Print Date : 17 NOV 21

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: Transferred to BAS*65079 on 23 AUG 21 W 1013 KEYST
 Estimate amount was 0.00 CUSTOMER STATES
 THAT WHEN THE SLIDE IN IS IN, THE RUBBER
 LP LINE THAT GOES TO THE REFRIGERATOR
 KINKS AND WONT ALLOW THE REFRIGERATOR TO
 WORK. CUSTOMER COMING BY 1ST THING 08/09
 TO HAVE THIS FIXED.
 CORRECTION: FOUND LINE KINKED AND I REMOVED LINE
 AND WE INSTALLED A NEW GAS LINE AND HAD
 TO INSTALLE A NEW COUPLER TO THE MAIN
 STEEL LINE AND THEN I RE ROUTED L
 GAS LINE TO KEEP IT FROM KINKING AGAIN.
2 COMPLAINT: CUSTOMER STATES THAT THE ARM ON THE W 1013 KEYST
 CHAIR CLOSEST TO THE DOOR IS LOOSE.
 CAUSE: TOOK PICTURES AND TURNED INT TO BEN TO
 GET APPROVAL FOR A NEW RECLINER.
3 COMPLAINT: Transferred to BAS*65079 on 23 AUG 21 W 1013 KEYST
 Estimate amount was 0.00 CUSTOMER STATES
 THAT SOME OF THE SCREWS ARE BACKING OUT
 OF THE ROAD SIDE PLASTIC WHEEL OPENING
 MOLDING.
 CORRECTION: FOUND LOOSE SCREWS AND SECURED THEM TO
 THE ALUMINUM STRIP BEHIND METAL.
4 COMPLAINT: CUSTOMER STATES THAT THE PLASTIC PEICE W 1013 KEYST
 ON GLASS SHOWER DOOR BROKE IN TRANSIT.
 THIS IS THE PLASTIC PEICE THAT HAS A
 SCREW IN IT THAT GOES THROUGH THE GLASS
 DOOR.
 CORRECTION: REMOUNTED HANDLE AND FIXED DOOR LOCK
5 COMPLAINT: CUSTOMER STATES THAT THE DRAWER NEAR THE W 1013 KEYST
 ENTERTAINMENT CENTER IS OUT OF
 ADJUSTMENT.
 CORRECTION: REMOVED DRAWER AND INSTALLED ON THE
 GUIDES RIGHT

Continued on page 2

Work Order : 64969

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
6       COMPLAINT:  SOFA RECLINER FOR JOB 2 THAT WAS CLAIMED W      1013    KEYST
      CORRECTION:  REMOVE WIREING AND REMOVE BACK. TAKE
                  BOLTS OUT OF BOTTOM TRACK. INSTALL NEW
                  CHAIR AND WIRE UP. MAKE SURE IT WORKED
                  ON THE SHORE CORD
7       COMPLAINT:  CUSTOMER STATES THAT THERE IS A CABLE          W      1013    KEYST
                  THAT HANGS DOWN FROM THE LIVING ROOM
                  SLIDE WHEN THE SDLIDE ROOM IS IN. THIS
                  CAN BE SEEN FROM THE INDIDE.
      CORRECTION:  THERE ARE 8 CABLES TO RUN THE ROOM IN
                  AND OUT. THEY ARE ALL WORKING FINE FOR
                  THE ROOM TO CLOSE TIGHT AND OPEN TIGHT
                  TO WALL. THIS IS COMMON FOR THE CABLES
                  TO SAG

```

```

*****
Job # Part No Description                PARTS                Bill to    Qty    Price    Total
*****
1      07-31485 3/8IN OEM LP SUPPLY HOSE, 72 W-1013          0      30.30      0.00
1      6090     REDUCER - LP                    W-1013          0       4.54      0.00
6      674226   SOFA-RECLINER-LHF-              W-1013          1     830.30     830.30

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
1 Z990     MISC LABOUR CODE (EXTE BRM W-1013          0.00    130.00      0.00
1 Z990     MISC LABOUR CODE (EXTE BRM W-1013          0.00    130.00      0.00
2 Z990     MISCELLANEOUS REPAIR    BB W-1013          0.50    130.00     65.00
2 Z990     MISCELLANEOUS REPAIR    BRM W-1013          0.50    130.00     65.00
3 Z990     MISCELLANEOUS REPAIR    BRM W-1013          0.00    130.00      0.00
4 Z990     MISCELLANEOUS REPAIR    BB W-1013          0.00    130.00      0.00
5 Z990     MISCELLANEOUS REPAIR    BB W-1013          0.00    130.00      0.00
6 Z990     MISCELLANEOUS REPAIR    BB W-1013          0.00    130.00      0.00
7 Z990     MISCELLANEOUS REPAIR    BB W-1013          0.00    130.00      0.00

```

```

*****
Job # Excode Description                EXTRAS                bill to    Qty    Price    Total
*****
1 SS     SHOP SUPPLIES                    W-1013          0.00      0.00      0.00
6 FRT    CRATE                            W-1013          1.00     50.00     50.00
6 FRT    FREIGHT                          W-1013          1.00    127.00    127.00

```

```

*****
                        CUSTOMER COMMENTS
*****
RECLINER IN SHOP 1A 9-30-21...CAM
BH SENT IN PREAUTH WAITING TO HEAR BACK
CALLED CUSTOMER HE SAID THEY ARE IN FLORIDA AND WILL GET WITH US TO
SCHEDULE APPT. 10-27-21 CJA

```

Continued on page 3

Work Order : 64969

BH GAVE TO AMANDA

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1013      830.30    130.00     0.00    177.00    0.00    1,137.30
      Totals      830.30    130.00     0.00    177.00    0.00    1,137.30
*****
```