

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13405B

Date In: 11 MAY 26 Author: KOTT
Promised Date: 25 DEC 26 Stock No: 11610
: Year: 2026
Customer Name: 6015 - THOMSEN, ALLEN Manufacturer: GRAND DESIGN
Address: 144925 DEER TRAIL LANE Brand: MOMENTUM G-CLASS
: MARATHON CITY, WI Model: 320G
Postal/Zip: 54448 Miles/Hrs: 0
Phone#(res): 715-359-9414 Exterior Color:
Phone#(bus): Unit Type: FWH-FW TOY HAULER
Cell Phone: License#:
Email: Tag#:
Purchased Date: 28 MAR 26 :
Delivery Date: 16 MAY 26 :
InService Date: :
Serial#: 573FM3821TBB05690 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - IN KITCH N LEFT SIDE W 1020 GRAND
CORNER TRIM HAS A CRACK AND LARGE GAP IN
TRIM WHERE THEY MEET IN CORNERS
CAUSE: Small crack from mfg in corner trim
CORRECTION: I used putty to fill the crack and the
upper corners on trim also REQ: .20
WARR COMPLAINT: WARRANTY REPAIR 2 -BEDROOM DOOR IS W 1020 GRAND
PEELING AT THE BOTTOM
CAUSE: Finish on door chipped and peeling
CORRECTION: Used wood marker to cover the bare areas
on edge and bottom of the door REQ: .20
WARR COMPLAINT: WARRANTY REPAIR 3 - REAR BATH DOOR IS W 1020 GRAND
PEELING AT THE BOTTOM
CAUSE: Peeling finish on bath door
CORRECTION: Used wood marker to cover missing finish
REQ: .10
WARR COMPLAINT: WARRANTY REPAIR 4 - WHEN BRINGING BED W 1020 GRAND
Down IN Garage the mattress tubbed
against the valance and it's bent
CAUSE: Mfg installed this valance so close to
bed lift if mattress is overhanging to
one side this will keep happening
CORRECTION: Used larger screws to reattach the
valance made sure the mattress is even
on the platform REQ: .30
WARR COMPLAINT: WARRANTY REPAIR 5 -AWNING OVER THE RAMP W 1020 GRAND
DROP DOWN DOOR IS CROOKED
```

Continued on page 2

Work Order : 13405B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Not a issue
CORRECTION: THIS IS NORMAL IT NEEDS TO HAVE A PITCH
           SO Water does not pool up on fabric
           nothing wrong with it DO NOT REQUEST
           ANYTHIGN FOR THIS LINE-

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR05 Z992     MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00

```

```

*****
Job #  Excode   Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00  0.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1020      0.00  280.00  0.00  0.00  0.00  280.00
Totals      0.00  280.00  0.00  0.00  0.00  280.00

```

&k2S
&k0S