



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65063
Promised Date: 31 AUG 21

CUSTOMER WORK ORDER

WO #: 65063

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: CAM
Location: 0825 CHECK PREAUTH

Stock #: 10793
Stock Desc: 2022 TT FOREST RIVER
CHEROKEE GREY WOLF 20RDSE
Chassis #: 5ZT2CKJB0NF000868
Serial #: 5ZT2CKJB0NF000868
Mileage:
Licence:

Invoice #:
Date In: 19 AUG 21
Promised: 31 AUG 21
Date Sched:
Completed: 26 AUG 21
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI - NEW TRAVEL TRAILER.

CORRECTION: Moved into shop from sales lot. Purged and filled LP tanks. Removed factory battery and battery box. Drilled drain holes in bottom of box. Remounted on frame in correct location. Reinstalled battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked awning and roof. Checked entrance door and all compartment doors. Checked power cord. Checked converter output. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked all GFCI outlets. Checked USB outlets. Filled fresh water tank and flushed antifreeze from all water lines and faucets. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from water lines. Performed LP drop test and set LP pressure at 11 in.wc. Filled all holding tanks and checked monitor panel. Recorded all serial numbers and took pictures. Retracted all stab jacks. Drained all holding tanks, including water heater. Applied all company decals. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE GFI RECEPTICLE IS NOT OPEN

CAUSE: THE GFCI OUTLET IS NOT WORKING.

CORRECTION: Checked all recepticals on GFCI circuit. None of them will trip GFCI. Removed GFCI from wall in bathroom. Checked for correct wires connected to line terminals. Both correct. Found a loose screw on back of receptical. Tightened screw. GFCI now working.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	39.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 39.00

Parts Total: 0.00
Labour Total: 39.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 39.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 26 Aug 2021

Customer Signature : _____

Customer Work Order

W/O: 65063
Promised Date: 31 AUG 21



Customer #: 1000
BASDEN'S AMERICAN RV,



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$130.00 OWNER INFORMATION	CLAIM STATUS Authorized CLAIM 734154 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CKJB0NF000868 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 086 / 086A ITEM # CKT20RDSE-86 DEALER RO # 65063 CLAIM START DATE 08/23/2021 CLAIM END DATE 01/01/1900 WARRANTY EXPIRATION DATE
Retail Date of Purchase	WARRANTY EXPIRATION DATE

Claim Line Details

Labor	Operation Code	Operational Description		
Line# 1	40-108-24-11-001334	110 Volt Interior Wiring - Electrical/110 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2021-08-23 11:09:45 :: THE GFI RECEPTICLE IS NOT OPEN THE GFCI OUTLET IS NOT WORKING. Checked all receptacles on GFCI circuit. None of them will trip GFCI. Removed GFCI from wall in bathroom. Checked for correct wires connected to line terminals. Both correct. Found a loose screw on back of receptacle. Tightened screw. GFCI now working.			
	Model #	Dir Sub Hrs	0.30	Sub Labor Amt \$39.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt \$39.00
	Notes			

Submitted	Labor Amt	\$39.00	Approved	Labor Amt	\$39.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$39.00		Total	\$39.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	