



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73207
Promised Date:
16 MAY 26



WO #: 73207 (Appointment Date: 16 APR 2026 - Time: 09:15am)

Customer Name: 19667 - STEIDER,
TIMOTHY D

Completed Date: 20 MAY 26

Invoice#:

Author: ADVISOR

Stock Desc: 9558 2026 BAY STAR 3225

Serial#: 142199

Chassis#: 1F66F5DN3S0A01256

Miles/Hrs: 1870

Tag#: 7206

Purchased Date: 27 DEC 25

Warranty Date: 27 DEC 25

Date In: 16 APR 26

Time In:

Job #1 - Internal

COMPLAINT: CUSTOMER STATES FRONT CAMERA SHOWS FAULT ON DASH **FRONT CAMERA
FAULT - SERVICE REQUIRED**

CORRECTION: Doesnt have front camera

Labor

Job #	Description	Total
1	CAMERA DASH FAULT	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES RECEIVED HOOD RECALL

CAUSE: Recall hood braket

CORRECTION: Added screws as recall work was required
Photos attached

Labor

Job #	Description	Total
2	BULLETIN - HOOD LATCH	37.00

Parts

Part #	Description	Qty	Price	Total
039707	LOCKNUT 10/24 NYLOCK 18-8	4.00	0.07	0.28
039708	WASHER FLAT 10SAE F/W 18-8	4.00	0.05	0.20
039709	PHILLIP PAN 10/24X1" 18-8	4.00	0.20	0.80

Subtotal for Job #2: 38.28

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES CARPET WRINKED AT BEDROOM SLIDE - BACK END

CAUSE: Carpet glue from factory came off

CORRECTION: Removed facia, added glue to the carpet. Reinstalled Fascia. The carpet is still creased.

Customer #: 19667
STEIDER, TIMOTHY D



Will need to see if the wrinkles flatten over time. Requesting 1.5Hours
Photos attached

Labor

Job #	Description	Total
3	CARPET JAMB	277.50

Subtotal for Job #3: 277.50

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES SAW DUST IN LIGHT BY DINETTE TABLE

CAUSE: .unknown

CORRECTION: Removed light cover, cleaned and removed saw dust, reinstalled light cover. Requesting .10

Labor

Job #	Description	Total
4	CEILING PUCK LIGHT	18.50

Subtotal for Job #4: 18.50

Job #5 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES BATTERY COMPARTMENT DOOR IS NOT LATCHING

CAUSE: Latch assembly was loose

CORRECTION: Adjusted and tightened the lock assembly .10 Requested
Photos attached

Labor

Job #	Description	Total
5	COMPARTMENT DOOR LATCH V LOCK	37.00

Subtotal for Job #5: 37.00

Job #6 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES LATCH ON SCREEN IS BROKEN - RED LATCH

CAUSE: Unknown.

CORRECTION: Screen door latch is broke needs to be ordered. Requesting .10
Photos attached

Labor

Job #	Description	Total
6	ENTRY DOOR SCREEN LATCH	46.25

Parts

Part #	Description	Qty	Price	Total
158023A	LOCK THUMB EXTERIOR SCREEN	1.00	3.86	3.86
	920			
158023B	LOCK THUMB INTERIOR SCREEN 920	1.00	5.69	5.69

Subtotal for Job #6: 55.80

Job #7 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES PASS. SIDE FRONT WINDOW SEEMS LIKE IT'S NOT SEALED ALL THE WAY

CAUSE: Dry window seal

CORRECTION: Lubricated seal. Requesting .20
Window works

W/O: 73207
Promised Date: 15 MAY 26



Customer #: 19667
STEIDER, TIMOTHY D



W/O: 73207
Promised Date: 15 MAY 26



Customer #: 19667
STEIDER, TIMOTHY D



Labor		
Job #	Description	Total
7	WINDOW	37.00
Subtotal for Job #7:		37.00

Job #NOTE - External

CUSTOMER WOULD LIKE TO KNOW WHERE THE STAR LINK CABLE ON THE ROOF MIGHT BE

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #NOTE:				0.00

Parts Total: 10.83
Labour Total: 453.25
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 464.08

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 20 May 2026

