



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65081
Promised Date: 25 AUG 21

CUSTOMER WORK ORDER

WO #: 65081

Customer: 51114 - ADAMS, DANIEL R. -
812-598-9698

Tag:

Author: BH

Location: 0827 CHECK PREAUTH

Stock #: 10636

Stock Desc: 2021 TT RIVERSIDE RV
RETRO 231EABH

Chassis #: 59CCC3921ML003535

Serial #: 59CCC3921ML003535

Mileage:

Licence:

Invoice #:

Date In: 23 AUG 21

Promised: 25 AUG 21

Date Sched:

Completed: 26 AUG 21

Warr. Date: 08 APR 21

Job #BUNKHOUSE - Warranty

PRE DELIVERY INSPECTION NEW BUNKHOUSE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	260.00

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	0.00	0.00
SS	SHOP SUPPLIES	0.00	0.00	0.00

Subtotal for Job #BUNKHOUSE: 260.00

Job #1 - Internal

LABOR FOR BUNKHOUSE 2 HRS AMERICAN RV SPLIT GOODWILL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE 110V OUTLET BEHIND THE TELEVISION IS INOPERATIVE.

CORRECTION: INSTALLED NEW OUTLET IN CEILING.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	26.00

Parts

Part #	Description	Qty	Price	Total
S817	S817 BLACK DUAL OUTLET W/WALL COVER PLATE	1.00	8.56	8.56

Subtotal for Job #2: 34.56

Job #3 - Warranty

COMPLAINT: FRESH TANK MONITOR IS NOT WORKING

CAUSE: CUT UNDERBELLY AND FOUND THAT VENT LINE WAS KINKED

CORRECTION: CUT UNDERBELLY AND FOUND THAT VENT LINE WAS KINKED, CUT KINK OUT OF



Customer #: 51114
ADAMS, DANIEL R.

HOSE, ACIDENTLY CUT FILL LINE HOSE IT WAS LAYING ON BLACK PLASTIC HAD TO REPLACE
HOSE FILLED TANK AND TAPED BACK UP ,ALL IS WORKING.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	130.00
Subtotal for Job #3:			130.00

Parts Total: 8.56
Labour Total: 416.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 424.56

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Aug 2021

W/O: 65081
Promised Date: 25 AUG 21



Customer #: 51114
ADAMS, DANIEL R.



10636 - 2021 TT RIVERSIDE RV RETRO 231EABH Ser#: 59CCC3921ML003535 RO 65081

Ben Hoffman <bhoffman@americanrvcenter.com>

Wed 8/25/2021 2:04 PM

To: Warranty Manager Riverside RV <warranty@goriversiderv.com>

Cc: BJ Wright <bjwright@americanrvcenter.com>

 2 attachments (663 KB)

photo_2636155097764417543.jpg; photo_4893121973803576751.jpg;

1. THE 110V OUTLET BEHIND THE TELEVISION IS INOPERATIVE.
 - a. THE OUTLET WAS DAMAGED AND NEEDED TO BE REPLACED
 - b. INSTALLED NEW OUTLET IN CEILING.
 - i. LABOR 0.2
2. THE FRESH TANK MONITOR IS NOT WORKING
 - a. CUT UNDERBELLY AND FOUND THAT VENT LINE WAS KINKED
 - b. CUT KINK OUT OF HOSE, PUT HOSE BACK TOGETHER, AND TAPED UP UNDER BELLY FILLED TANK AND TAPED BACK UP, ALL IS WORKING.
 - i. LABOR 1.00

BEN HOFFMAN

SERVICE EXPERT

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. BHOFFMAN@AMERICANRVCENTER.COM