



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79843



CUSTOMER WORK ORDER

WO #: 79843

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0515 CHECKWORK

Stock #: 11750
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 16LP
Chassis #: 5ZT2CKEC1TY042695
Serial #: 5ZT2CKEC1TY042695
Mileage: 0
Licence:

Invoice #:
Date In: 06 MAY 26
Promised:
Date Sched:
Completed: 16 MAY 26
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SCREEN DOOR LATCH ON THE ENTRY DOOR NEEDS ADJUSTED

CAUSE: Latch pushed down too far

CORRECTION: Adjusted latch up

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #1: 39.00

Job #2 - Warranty

COMPLAINT: THE WATER HOOK UP PANEL IS BENT REALLY BAD

CAUSE: Bad factory install

CORRECTION: Remove and replace panel

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
F100069176	WATER FILL, CITY & GRAVITY COMBO - B	1.00	7.76	7.76

Subtotal for Job #2: 66.26

Job #3 - Warranty

COMPLAINT: ENTRY DOOR IS HARD TO CLOSE

CAUSE: Striker plate adjusted too far inward

CORRECTION: Adjusted plate outward

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	58.50

Subtotal for Job #3: 58.50

Job #4 - Warranty

COMPLAINT: STAPLE HOLES ABOVE THE DINNETT NEEDS TO BE FILLED

CAUSE: Factory missed the staple holes

CORRECTION: Filled with wood putty

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	19.50

Subtotal for Job #4: 19.50

Job #5 - Warranty

COMPLAINT: NASTY WOOD SPLINTER BETWEEN UPPER CABINET AND INTERIOR WALL

CAUSE: Poor craftsmanship

CORRECTION: Broken splinter off then pushed remaining up

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #5: 39.00

Parts Total: 7.76
Labour Total: 214.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 222.26

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 May 2026



Customer #: 1000
BASDENS AMERICAN RV,

