



Pre-Authorization

Pre-Authorization number	PREAUTH104158 (PA03995310	Reference no.79755	Status	Approved
--------------------------	------------------------------	--------------------	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd
Evansville, IN 47725 VIN 4YDFCGP25T2506575 Retail sold on

Root		Approved Actual				Base	Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
5104402A	Switch, 12V - Repair	0	0.2	0.2		1	Complaint: SWITCH FOR PORCH IS PUSHING OUT Cause: Wiring behind switch pushing it out Correction: Rearranged wiring and reinstalled switch
3100802F	Cabinet Door - Adjust	0	0.1	0.1		1	Complaint: BED ROOM CABINET DOORS ARE RUBBING Cause: Hinges out of adjustment Correction: Adjusted hinges. Doors no longer contact
6103815B	Shower/Tub Faucet - Shower Head	0	0.2	0.2		1	Complaint: SHOWER HEAD LEAKING Cause: Seal needed to be reseated Correction: Reseated seal and pressure tested. No leaks
3200102F	Door - Interior Hinged - Adjust	0	0.9	0.5		1	Complaint: PATIO DOOR IS HARD TO CLOSE Cause: Door is unadjustable. Door plate is too thick Correction: Fabricated new plate out of sheet metal KRV – Labor time adjusted allowing for proper repair procedure to be performed

Pre-Authorization number: PREAUTH104158 1

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.