



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79785
Promised Date:
20 MAY 26



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 79785

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0511 CHECK PREAUTH

Stock #: 11757

Stock Desc: 2026 5W KEYSTONE

COUGAR HALF-TON 2400RE

Chassis #: 4YDFCGL22TV506005

Serial #: 4YDFCGL22TV506005

Mileage: 0

Licence:

Invoice #:

Date In: 30 APR 26

Promised: 30 MAY 26

Date Sched:

Completed: 12 MAY 26

Warr. Date:

Job #PDINFW - Internal

PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: RECLINER CONTROLLS ARE BACKWARDS

CAUSE: The controller for the left recliner is working on the right side.

CORRECTION: Removed the mounting screws. Pulled the recliner out. Located control wires and swapped them. Tested function. Placed recliner back in place and secured it to the floor with the mounting screws.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	57.00

Subtotal for Job #1: 57.00

Job #2 - Warranty

COMPLAINT: SCREEN DOOR IS HITTING LATCH

CAUSE: The screen door is hitting the latch.

CORRECTION: Moved the latch over with a hammer.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	38.00





Subtotal for Job #2: 38.00

Job #3 - Warranty

COMPLAINT: BATHROOM SLIDING DOOR IS RUBBING SSTILE

CAUSE: The door is hitting the stile.

CORRECTION: Backed the screws out a little to clear the door.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	38.00

Subtotal for Job #3: 38.00

Job #4 - Warranty

COMPLAINT: CABINET DOOR NEXT TO SINK IS RUBBING

CAUSE: The top of the doors are rubbing.

CORRECTION: Took a hammer and pushed the doors away from each other.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	19.00

Subtotal for Job #4: 19.00

Job #5 - Warranty

COMPLAINT: BEDROOM DOOR IS HITTING THE DOORR FRAME

CAUSE: The top of the door is hitting the frame.

CORRECTION: Took a hammer and pushed the frame over.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	19.00

Subtotal for Job #5: 19.00

Job #6 - Warranty

COMPLAINT: MARKS ON MIRROR IN BEDROOM

CAUSE: Marks on the mirror in bedroom.

CORRECTION: Cleaned mirror with glass cleaner.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: BRAKE AWAY CABLE IS DAMAGED

CAUSE: Damaged section of the breakaway cable.

CORRECTION: Replaced breakaway cable.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	38.00

Parts



Part #
17-0181

Description
ZIP 6FT BREAKAWAY CABLE AND PIN

Qty
1.00

Price
15.86

Total
15.86

Subtotal for Job #7:

53.86

Parts Total: 15.86

Labour Total: 209.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 224.86

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 May 2026

Customer Work Order

W/O: 79785
Promised Date: 30 MAY 26



Customer #: 1000
BASDENS AMERICAN RV,

