

GREENEWAY, INC.  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS WI  
 US  
 54494  
 (715) 325-5170

WORK ORDER # 13428

Date In: 28 APR 26	Author: MGRAY
Promised Date: 07 MAY 26	Stock No:
:	Year: 2018
Customer Name: 1020 - GRAND DESIGN	Manufacturer: GRAND DESIGN
Address: 11333 COUNTY RD 2	Brand: SOLITUDE
: MIDDLEBURY, IN	Model: 310GK
Postal/Zip: 46540	Miles/Hrs:
Phone#(res): 888-825-2820	Exterior Color:
Phone#(bus):	Unit Type: FW-FIFTH WHEEL
Cell Phone:	License#:
Email: NONE	Tag#: emailed est 5/8
Purchased Date:	:
Delivery Date:	:
InService Date:	:
Serial#:	:

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT: INTERIOR STEP RECALL - PARTS TAGGED ON PARTS SHELF CAUSE: Interior step recall. CORRECTION: Installed brackets under steps.		W	1020 GRAND
2	COMPLAINT: BRACKET INSTALL CAMPAIGN CAUSE: Step bracket install. CORRECTION: Done.		W	1020 GRAND
3	COMPLAINT: WOULD LIKE QUOTE ON REAR HITCH INSTALL FOR BIKE RACK. NEED PART PRICING AND BDT QUOTE TO WELD IN. CAUSE: Estimate for rear bumper hitch install. CORRECTION: REFER TO LINE #6 - BOLT IN AND #7 WELD IN		E	8957 GURAL
RI	COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF REPAIR IS NEEDED. CAUSE: Roof inspection. CORRECTION: The roof looks good for the most part. It will need a new mushroom vent. The one on there is cracked. REFER TO LINE #8		I	PD GOODW
5	COMPLAINT: CHECK OVER SEALS AND SEALANT ON UNIT FOR ESTIMATE ON REPAIR/REPLACE/ CAUSE: Check all sealants on exterior. CORRECTION: All looks good.		E	8957 GURAL
4	COMPLAINT: LIGHT STRIPS ON FRONT CAP ARE NOT WORKING. CHECK OUT FOR ESTIAMTE. CAUSE: Check front cap lights for operation. They don't turn on. Found out that the		E	8957 GURAL

Continued on page 2

Work Order : 13428

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
        wire was disconnected from the switch.
        Hooked it back up and they work. But the
        ods strip light has a lot of LEDs burnt
        out. See if customer wants all of them
        replaced. Need 2- 6' strips. White light
        and 1-1' light.
CORRECTION: ...
6  INSTALL BOLT ON REAR HITCH                E      8957   GURAL
7  INSTALL WELDED ON HITCH                  E      8957   GURAL
8  COMPLAINT:  REPLACE MUSHROOM VENT ON UNIT ROOF  E      8957   GURAL
    CAUSE:    Mushroom vent is cracked.
CORRECTION:  Installed new mushroom vent.
*****
```

```
*****
Job # Part No   Description                PARTS   Bill to   Qty   Price   Total
*****
1      822093414  STEP TREAD ANGLE BRACKET W-1020    2     7.38   14.76
1      822061989  SCREW 8 X 3/4 RD WASHER W-1020   18     0.07    1.26
7      EST      ADJUSTABLE RECIEVER .HITC E-8957    0    43.00    0.00
6      EST      BOLT ON RECIEVER B100   E-8957    0    43.00    0.00
8      756815008754 MUSHROOM STYLE PLUMBING E-8957    1     8.06    8.06
4      EST      420655 - LIGHT EXTERIOR E-8957    0    43.00    0.00
*****
```

```
*****
Job# Lab Code Description                LABOUR   Mech Bill to   Hrs   Rate   Total
*****
  1 Z992  MISC LABOUR CODE (WARR TD W-1020    0.50  140.00  70.00
  2 Z992  MISC LABOUR CODE (WARR TD W-1020    0.50  140.00  70.00
  3 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.00  140.00   0.00
RI Z991  PREFORM ROOF INSPECTIO TD I-PD     0.00   70.00   0.00
  5 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.05  140.00   7.00
  4 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.50  140.00  70.00
RI Z991  PREFORM ROOF INSPECTIO TD I-PD     0.30   70.00  21.00
  5 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.79  140.00 110.60
  3 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.40  140.00  56.00
  6 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.00  140.00   0.00
  7 Z990  MISC LABOUR CODE (EXTE TD E-8957    0.00  140.00   0.00
  8 F960  VENT CAP, R & R           TD E-8957    0.20  140.00  28.00
  4 Z990  FRONT CAP LIGHT R&R      E-8957    0.00  140.00   0.00
*****
```

```
*****
Job # Sublet Description                SUBLET   bill to   Vendor   Total
*****
  7 BDT WELDING.                        E-8957   329-BDT INC  0.00
*****
```

```
*****
Job # Excode Description                EXTRAS   bill to   Qty   Price   Total
*****
  1 SSE      SHOP SUPPLIES - EXTERNAL W-1020    1.00  20.37  20.37
*****
```

Continued on page 3

Work Order : 13428

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
   4   M        STRIP LIGHTS      E-8957     0.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E   8957          8.06    271.60    0.00     0.00    15.41    295.07
I   PD           0.00     21.00    0.00     0.00     0.00     21.00
W  1020          16.02    140.00    0.00    20.37     0.00    176.39

      Totals      24.08    432.60    0.00    20.37    15.41    492.46
*****
```

&k2S  
&k0S