

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2677451
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVFC0TG815460
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 452 / 452
 ITEM # AVT17DBX-452
 DEALER RO # 73356
 CLAIM START DATE 05/15/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-474-12-00-003344	Operational Description Bracket - Interior/Appliance Securement/Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction	
	Original Note : stephanie@dealer-advisors.com, 2026-05-15 12:48:54 :: Complaint: Refrigerator is loose Cause: Found refer came loose from rear mounting bracket. Found a self tapping screw drilled through the bottom hinge on the left side of the refer door to hold it into the hole. Remove the screw and pull the refer out to examine the mounting bracket, found it was still screwed into the floor. However, putting the refer back in to test the mounting bracket it was found that the refer would go too far into the cabinet not allowing the door to be opened. Correction: Move the mounting bracket forward about one inch. Now the refer will not tip out or tip forward. The original screw that was run though the hinge was put back into place.	
Model#	Dlr Sub Hrs 0.70	Sub Labor Amt \$133.00
Serial#	Appr Hrs 0.70	Appr Labor Amt \$133.00
	Notes Authed	

Submitted	Labor Amt	\$133.00	Approved	Labor Amt	\$133.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$133.00		Total	\$133.00

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.