

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2674705
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2RPHC8KV016442
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	047 / 047D
OWNER INFORMATION		ITEM #	RPT190-47
JEFFREY HAGEMANN		DEALER RO #	73321
1704 NOTRE DAME DR NE		CLAIM START DATE	05/13/2026
Albuquerque, NM 87106		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/09/2019	WARRANTY EXPIRATION DATE	05/09/2020

Claim Line Details

Labor

Line# 1	Operation Code SB-467-13--003293	Operational Description 51-1058 - MEDICINE CABINET MAY FALL - Technical Service Bulletin/Medicine Cabinet/Relocate/
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-05-13 14:48:07 :: Active TSB for medicine cabinet Medicine cabinet is not attaching. Used heavy duty magnet and found attachment points, scoot over three inches and resecured. Used matching wall color stop to cover the old holes.	
Model#	Dlr Sub Hrs	1.00
Serial#	Appr Hrs	1.00
	Sub Labor Amt	\$190.00
	Appr Labor Amt	\$190.00
	Notes authorized to preform TSB	

Labor

Line# 2	Operation Code RC-632-03-00-003938	Operational Description 20V763, 2020-606 - PLUMBING CONCERNS - Recall/Plumbing/Install/No Tread Code
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-05-13 14:50:24 :: Active recall for sewer termination bracket Old bracket is holding, will need to install the plumbers tape when it arrives using guidelines from manufacturer	
Model#	Dlr Sub Hrs	0.30
Serial#	Appr Hrs	0.30
	Sub Labor Amt	\$57.00
	Appr Labor Amt	\$57.00
	Notes authorized to preform recall as stated	

Submitted	Labor Amt	\$247.00	Approved	Labor Amt	\$247.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$247.00		Total	\$247.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.