



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72713
 Promised Date:
 12 MAY 26



WO #: 72713
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 12 MAY 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9643 2026 OPEN RANGE
 COLT 17BH
 Serial#: 58TBM0AJ8T7V53121
 Chassis#: 58TBM0AJ8T7V53121
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 25 NOV 25
 Time In:

Job #1 - Internal

Transferred to RV*72713-1 on 16 JAN 26
 Estimate amount was 0.00
 CHECK IN NEW UNIT

Subtotal for Job #1: 0.00

Job #PDI1 - Internal

COMPLAINT: Transferred to RV*72713-1 on 16 JAN 26
 Estimate amount was 0.00
 PRE-PDI NEW TT - 3.0

CAUSE: PDI NEEDED

CORRECTION: PDI COMPLETED

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: Transferred to RV*72713-1 on 16 JAN 26
 Estimate amount was 0.00
 WINTERIZE STANDARD

CAUSE: Winterize unit.

CORRECTION: Unit has been winterized.

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #WIN-STD: 0.00

W/O: 72713
Promised Date: 15 MAY 26



Job #2 - Warranty

COMPLAINT: LP hose to regular was damaged by transport driver.
Reinstall LP line to regulator & perform drop test

CAUSE: Lp pigtail was damaged when coach was being unloaded by transport driver.
Replace and preform. Drop test

CORRECTION: Removed LP pigtail and replaced with new one. Perform drop test on unit, unit passed.

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	134.25

Parts

Part #	Description	Qty	Price	Total
94-3740	INLET FITTING	1.00	1.74	1.74
06-0383	24" RUBBER PIGTAIL	1.00	24.06	24.06

Subtotal for Job #2: 160.05

Job #3 - Warranty

COMPLAINT: Metal on cap is damaged behind regular when lp line was hit by transport driver.

CAUSE: Cap metal is damaged behind LP regulator due to transport driver.
Broke at delivery

CORRECTION: Remove and replace cap metal with new piece. Psrt on order.
Removed damage front exterior panel, including removal of existing fasteners and careful separation to prevent damage to adjacent components and structure. Cleaned and prepped mounting surfaces by removing old sealant, adhesive residue, and debris to ensure proper adhesion to the fitment of new panel. Installed new front exterior panel, align with factory body lines and verifying proper fitment across all edges and seams. Applied sealant where required to maintain weather resistance and structural integrity. Secured panel using appropriate fasteners, ensuring even distribution and proper torque. Transfer all factory decals and safety labels from original panel. Carefully measured, aligned and install decals to match OEM placement for complaints and visual accuracy. Insured proper adhesion and unlimited air pockets for long-term Durability.
For final inspection of panel alignment, seals integrity, and overall appearance. Verified all details are present, legible, and correctly position per manufacturer standards. Clean work area and confirmed unit is returned to proper operating in cosmetic condition

Labor

Job #	Description	Total
3	METAL	1,074.00

Parts

Part #	Description	Qty	Price	Total
0344499	DECAL, EXTERIOR MULTIPLE 21 X 13.50	1.00	3.60	3.60
0870168	METAL 24" X 96" POLAR WHITE CLEAR COAT S-LOCK MESA	1.00	291.27	291.27
40170	SILICONE TUBE-CLEAR	1.00	14.56	14.56
20-1400	25' VINYL INSERT BLK	1.00	10.60	10.60

Subtotal for Job #3: 1,394.03

Job #4 - Warranty

COMPLAINT: Reinstall LP line to regulator & perform drop test

CAUSE: Replace and preform. Drop test

CORRECTION: Perform drop test on unit ,unit passed.

Customer #: 1000
MYERS "RV" CENTER,
INC.,



Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	3.72	18.60
Subtotal for Job #4:				18.60

Parts Total: 364.43
 Labour Total: 1,208.25
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 1,572.68

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 12 May 2026

W/O: 72713
 Promised Date: 15 MAY 26



Customer Order

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,

