

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13375

Date In: 17 APR 26 Author: DLUCAS  
Promised Date: 25 DEC 26 Stock No: 11241  
: Year: 2025  
Customer Name: 98898 - LENZINI, RICHA Manufacturer: CROSSROADS  
Address: 8211 15TH AVE Brand: HAMPTON  
: KENOSHA, WI Model: 372FDB  
Postal/Zip: 53143 Miles/Hrs: 0  
Phone#(res): 262-654-0560 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: DREAMVETTE74@WI.RR.COM Tag#: DB: - 5/20  
Purchased Date: 20 SEP 25 :  
Delivery Date: 27 OCT 25 :  
InService Date: :  
Serial#: 4YDTHPT2XS9330185 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
SC CUSTOMER REQUESTS SERVICE CALL TO N10831 11TH AVE E 98898 LENZI  
NECEDAH  
1 COMPLAINT: CUSTOMER STATES AC UNIT IN THE VERY W 1047 CROSS  
FRONT ON UNIT TURNS ON AND GETS HOT AND  
VERY LOUDS SHUTS OF AND REPEATS  
CAUSE: the ac compressor would intermittently  
come on no fan even when thermostat was  
off or disconnected diagnose bad control  
board for this coleman ac pics taken  
model and the Part I used  
CORRECTION: after install of new control module for  
ac the compressor stay off now I also  
tested ac outside temp was 74 degrees  
air coming out of ac is 48 degrees  
delta temp of 26 degrees amp draw of 9.0  
ac is working correctly REQUEST:1.5  
approved: 1hr  
2 COMPLAINT: CUSTOMER STATES LEAK COMING FROM BLACK W 1047 CROSS  
TANK DISCHARGE ON UNIT WOULD LIKE  
ADDRESSED  
CAUSE: multiple pics taken What I found for  
discharge pipe the banjo connector  
prongs was stretched not sealing  
correctly when draining 1 banjo  
connector and 1 fernco used. but also he  
will need a new floor vent due to me  
stepping on it measurements and pics  
taken he said send to his address

Continued on page 2

Work Order : 13375

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: after replacing the connector on
              discharge pipe I also tested no more
              leaks

```

```

*****
Job # Part No      Description           PARTS      Bill to   Qty      Price      Total
*****
1      755790202010 COOL CONTROL PACKAGE      W-1047     1        73.66     73.66
2      019079102805 ROTATING RIGID PIPE ADAP W-1047     1         8.98      8.98
2      119253          3" COUPLING              W-1047     1         4.10      4.10

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to   Hrs      Rate      Total
*****
1 WARR      MANUFACTURER WARRANTY JS      W-1047     1.70     140.00    238.00
2 WARR      MANUFACTURER WARRANTY JS      W-1047     1.20     140.00    168.00

```

```

*****
Job # Excode Description      EXTRAS      bill to   Qty      Price      Total
*****
SC SSE      SHOP SUPPLIES - EXTERNAL E-98898    1.00     0.00      0.00
SC SC       SERVICE CALL          E-98898    33.00     3.75     123.75

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E 98898           0.00       0.00       0.00       123.75     6.81     130.56
W 1047           86.74     406.00     0.00       0.00       0.00     492.74

Totals           86.74     406.00     0.00       123.75     6.81     623.30

```

&k2S  
&k0S