

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 13170

Date In: 19 DEC 25 Author: KOTT
 Promised Date: 31 DEC 26 Stock No: 11572
 : Year: 2026
 Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
 Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION
 : WISCONSIN RAPIDS, WI Model: 20BHCE
 Postal/Zip: 54494 Miles/Hrs: 0
 Phone#(res): 800-758-2272 Exterior Color:
 Phone#(bus): Unit Type: TT-TRAVEL TRAILER
 Cell Phone: License#:
 Email: NONE Tag#: PARTS INQUIRY 4/27
 Purchased Date: :
 Delivery Date: :
 InService Date: :
 Serial#: 5ZT2PUJB9T4026880 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
NTTS COMPLAINT: NEW TRAVEL TRAILER STOCK PREP I PDI PRE-D
CAUSE: Done with prep
CORRECTION: Done
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF I PDI PRE-D
CONTAINED - TOWABLE
CAUSE: Done
CORRECTION: Done
CEN COMPLAINT: CLEAN EXTERIOR- NEW I PDI PRE-D
CAUSE: New unit needs desalting
CORRECTION: Desalted and washed
WARR COMPLAINT: WARRANTY REPAIR 1 - The 751 key to W 1021 FORES
unlock the compartment doors is missing
CAUSE: The 751 key for the compartment doors
was missing, i got a new one from parts
CORRECTION: Done REQ: .10
WARR COMPLAINT: WARRANTY REPAIR 2 -the main door is W 1021 FORES
sticking when shut so its hard to open
CAUSE: The main door is not closing properly.
The door is slightly warped to where the
latch will not sit into the striker
plate. We will have to order a new door.
H:72 1/4 W:26 1/4
CORRECTION: R&R ENTRY DOOR REQUEST: 1.50 NOTING-
PER EVAN, WHEN HE WENT OUT TO GET THE
MEASUREMENTS FOR THE DOOR THAT WARRANTY
REQUESTED HE FOUND THAT THE DOOR WAS
OKAY AGAIN- MAY BE FROM THE WARM WEATHER
SHIFTING TO COLD WEATHER-
```

Continued on page 2

Work Order : 13170

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 - the dust cover will  W    1021   FORES
        CAUSE:      The compartment door locks were sticking
                   a lot from salt getting into them, i
                   tried to use silicone lube on it bit it
                   didnt help, i had dave order 3 new locks
                   and installed them
        CORRECTION: Done  REQ: .75 WARR AUTH: .30
WARR    COMPLAINT:  WARRANTY REPAIR 4 - the entry steps have W    1021   FORES
        CAUSE:      The entry steps has 3 pretty deep
                   gouges, we will have to order new steps
        CORRECTION: R&R ENTRY STEPS  REQUEST: .50
WARR    COMPLAINT:  WARRANTY REPAIR 5 - The forest river      W    1021   FORES
        CAUSE:      The forest river decal on the front cap
                   is peeling and tearing and will have to
                   be replaced Stickers are peeling off the
                   front cap
        CORRECTION: Replace it with new stickers  REQUEST:
                   .50   WARR AUTH: .50

```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
NTTS  8220BG24      GROUP 24 BATTERY BOX SNA I-PDI           1    10.36   10.36
WS    009114950003  -50 F GLYCERIN FREE BASE I-PDI           3     6.62   19.86
WARR0 028985941521    CH 751 HURD KEY           W-1021          1     3.25    3.25
WARR0 756815003254  CMPRTMNT DOOR KEY LOCK    W-1021          3     8.14   24.42
WARR0 8220614635     DECAL, LARGE FOREST RIVE W-1021          1    20.82   20.82

```

```

*****
Job#  Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           1.03  70.00  72.10
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.47  70.00  32.90
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.55  70.00  38.50
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.26  70.00  18.20
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           1.39  70.00  97.30
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.63  70.00  44.10
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.04  70.00   2.80
NTTS  RV1F-1A    NEW STOCK PREP           EG    I-PDI           0.13  70.00   9.10
WS    W495       WINTERIZE RV (WATER SY EG    I-PDI           0.32  70.00  22.40
WS    W495       WINTERIZE RV (WATER SY EG    I-PDI           0.38  70.00  26.60
CEN   CE        CLEAN EXTERIOR           HOD   I-PDI           0.70  70.00  49.00
ARR01 Z992      MISC LABOUR CODE (WARR EG    W-1021          0.10 140.00  14.00
ARR02 Z992      MISC LABOUR CODE (WARR EG    W-1021          0.50 140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR EG    W-1021          0.36 140.00  50.40
ARR03 Z992      MISC LABOUR CODE (WARR EG    W-1021          0.01 140.00   1.40

```

Continued on page 3

Work Order : 13170

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR03 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.13   140.00   18.20
ARR04 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR EG  W-1021    0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.00   140.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR JL  W-1021    0.00   140.00    0.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00
ARR05  FRT        FREIGHT      W-1021    1.00   42.96   42.96
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I    PDI          30.22    413.00    0.00     0.00     0.00    443.22
W    1021         48.49    364.00    0.00    42.96     0.00    455.45

Totals          78.71    777.00    0.00    42.96     0.00    898.67
*****
```

&k2S
&k0S