



leaking on the jack. need to replace jack.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	117.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
497030	8K JACK LEG ALUMIN	1.00	423.36	423.36

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JACK	1.00	29.01	29.01

Subtotal for Job #3: 569.37

Job #4 - Warranty

COMPLAINT: TRIM PIECE ON THE TABLE SLIDE NEEDS TRIMMING ON THE DOOR SIDE REAR SLIDE IT IS BOWED

CAUSE: trim piece is pushing out from wall

CORRECTION: trimmed the bottom of the piece. secured to the wall with brad nails.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	39.00

Subtotal for Job #4: 39.00

Job #7 - Internal

COMPLAINT: LEFT SIDE BASEMENT STORAGE LIGHT STAYS ON WHEN SET ON MOTION DETECTION ON THE DRIVERS SIDE

CAUSE: LIGHT WAS NOT ON THE CORRECT SETTING.

CORRECTION: TURNED SWITCH TO "MOTION" LIGHT FUNCTIONS CORRECTLY.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #7: 0.00

Job #8 - External

RASIE ALL 6 LEVELING CYLINDERS BY ONE HOLE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #8: 0.00

Job #9 - Warranty

KITCHEN GRAY WATER TANK VALVE LEAKS WHEN CLOSED ITS THE BACK

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	ZMS	65.00
Z990	MISCELLANEOUS REPAIR	ZMS	39.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

