

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13179

Date In:	09 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	9666
:	:	Year:	2020
Customer Name:	1808 - GIESE, JULIE	Manufacturer:	GRAND DESIGN
Address:	23 W. MAIN STREET	Brand:	MOMENTUM M-CLASS
:	HILBERT, WI	Model:	381M
Postal/Zip:	54129	Miles/Hrs:	:
Phone#(res):	920-418-5908	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	JGIESE4@OUTLOOK.COM	Tag#:	DB: 1/9- CMR PUT A MAS
Purchased Date:	06 NOV 19	:	:
Delivery Date:	29 FEB 20	:	:
InService Date:	:	:	:
Serial#:	573FM4536L1116061	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - CSC - VISUAL          W    1020    GRAND
          INSPECTION FOR MOMENTUM AND SOLITUDE
          UPPER DECK WALL SECUREMENT
          CAUSE:      Service campaign. There are two panels
                     on the inside that are damaged at the
                     bottom but the damage can be covered by
                     baton strips. found cracks in the frame
                     that will need to be repaired- will also
                     need to install lag bolts.
          CORRECTION: ... visual inspection complete.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CSC - 920018 - TO      W    1020    GRAND
          COMPLETE REPAIR FOR CAMPAIGN
          CAUSE:      need to install lag bolts and have the
                     frame repaired due to cracks. There is a
                     crack on the main lower beam on the ds
                     of the bulk head on the bottom-
          CORRECTION: REQUEST: 5.9  customer satisfaction
                     program
RI       COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF      I    PD      GOODW
          REPAIR IS NEEDED.
          CAUSE:      1001 CUSTOMER REQUESTED There are a few
                     pin holes in the dicor. One tube of
                     dicor. Next to the middle a/c the
                     decking has some strange bubbling going
                     on. I don't see any punctures in the
                     membrane and the decking isnt soft. It
                     almost seems like puddles of glue under
                     the membrane. We will just have to keep
```

Continued on page 2

Work Order : 13179

Job #	Description	JOB INFORMATION	Type	Bill To

	an eye on it to see if anything changes.			
	CORRECTION: ...			
1	ROOF RESEAL		E	1808 GIESE
WARR	COMPLAINT:	WARRANTY REPAIR 3 - WALL REPAIR FROM	W	1020 GRAND
	CAMPAIGN DAMAGES.			
	CAUSE:	There are two panels on the inside that		
		are damaged at the bottom but the damage		
		can be covered by baton strips.		
	CORRECTION: ... REQUEST 2.0 -			

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total

WARR0	8220961661	BOLT 1/2 - 6 X 3 - 1/2"		W-1020	6	1.05	6.30
WARR0	822061671	BOLT 1/2 -6 x 5 HEX LAG		W-1020	6	1.98	11.88
WARR0	822061052	SEALANT SIKAFLEX 252 WHI		W-1020	1	30.03	30.03
1	677917009213	DICOR SELF LEVELING LAP		E-1808	0	12.80	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total

ARR01	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.50	140.00	70.00
ARR01	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.00	140.00	0.00
ARR02	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.00	140.00	0.00
ARR02	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.00	140.00	0.00
ARR02	WARR	MANUFACTURER WARRANTY	JGK		W-1020	0.00	140.00	0.00
	RI Z991	PREFORM ROOF INSPECTIO	JGK		I-PD	0.30	70.00	21.00
	RI Z991	PREFORM ROOF INSPECTIO	JGK		I-PD	0.00	70.00	0.00
	1 Z990	MISC LABOUR CODE (EXTE			E-1808	0.00	140.00	0.00
ARR03	Z992	MISC LABOUR CODE (WARR			W-1020	0.00	140.00	0.00
ARR03	RV30G-3	MOLDING R&R FLAT/CORNE			W-1020	0.00	140.00	0.00
ARR02	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.50	140.00	70.00
ARR02	Z992	MISC LABOUR CODE (WARR	JGK		W-1020	0.00	140.00	0.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total

ARR02	FRT	FREIGHT		W-1020	1.00	16.01	16.01
ARR02	FRT	FREIGHT		W-1020	1.00	17.41	17.41
1	SSE	SHOP SUPPLIES - EXTERNAL		E-1808	1.00	0.00	0.00

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

I	PD	0.00	21.00	0.00	0.00	0.00	21.00
W	1020	48.21	140.00	0.00	33.42	0.00	221.63

Continued on page 3

Work Order : 13179

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	48.21	161.00	0.00	33.42	0.00	242.63

&k2S
&k0S