

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13182

Date In: 09 JAN 26 Author: KOTT
Promised Date: 01 MAY 26 Stock No: 11371
: Year: 2025
Customer Name: 13977 - TOMSCHIN, PAME Manufacturer: FOREST RIVER
Address: W14371 COTTONVILLE LAN Brand: FLAGSTAFF MICRO-LITE
: COLOMA, WI Model: 22FBS
Postal/Zip: 54930 Miles/Hrs: 0
Phone#(res): 715-228-4105 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: 715-570-2721 License#:
Email: TOMSCHIN@UNIONTEL.NET Tag#:
Purchased Date: 04 APR 25 :
Delivery Date: 31 MAY 25 :
InService Date: :
Serial#: 4X4TFLX27SD465207 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: CUSTOMER STATES THAT BLEW OPEN AND IT IS W 1021 FORES
BENT- NEEDS TO BE LOOKED AT- ODS FRONT
COMPARTMENT- the lock is in a ziplock
baggy just inside the front door.
***PLEASE SAVE THE STRING THAT THE
CUSTOMER USED TO TIE THE DOOR CLOSED***
CAUSE: Blew open and bent front storage
compartment
CORRECTION: Can be fixed with a new lock, but
storage door does have slight bend in it
REQ: 1.50
2 COMPLAINT: CUSTOMER STATES THAT HOT WATER DOES NOT W 1021 FORES
LIKE TO STAY LIT ON GAS- IT DOES LIGHT
ON GAS, BUT IT DOES NOT STAY LIT-
CUSTOMER STATES THAT IT DOES HAVE A HARD
TIME LIGHTING ON GAS AS WELL- THIS WAS
PREVIOUSLY LOOKED AT LAST FALL
CAUSE: Took everything apart on the hot water
heater cleaned it did testing on
solenoid. Those were fine. Move the
igniter to the middle of the tube seen
that was out of a line.
CORRECTION: Moving the igniter to the middle of the
tube seem to fix the problem. I ran it
for two hours and it lit up every time.
Will need a new PT valves has a steady
drip when it gets pressurized REQ 1
HOUR OF LABOR

Continued on page 2

Work Order : 13182

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
3      COMPLAINT:  CUSTOMER STATES THAT THE TV DOES NOT GET W   1021   FORES
      RECEPTION- IT WAS IN LAST FALL AND WE
      REPLACED THE ANTENNA- THEY ARE NOT
      GETTING ANY CHANNELS AT ALL- THEY HAVE
      TRIED THE ANTENNA BOTH IN CAMPGROUNDS
      AND AT HOME- IF THERE IS NO PROBLEM
      FOUND, CUSTOMER WOULD LIKE TO BE SHOWN
      HOW TO OPERATE IT-
      CAUSE:      Have to do an antenna scan
      CORRECTION: Have to go into the menu and do an
      antenna scan and make sure on the
      antenna by the back of the camper make
      sure its on had six channels inside the
      shop and 13 channels outside   REQ: .50
RI     COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF   I     PD     GOODW
      REPAIR IS NEEDED.
      CAUSE:      1001 CUSTOMER REQUESTED
      CORRECTION: Did not see anything wrong with the roof
      at this time
WS     COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF   E     13977  TOMSC
      CONTAINED - TOWABLE
      CAUSE:      Had to on winterize it to check hot
      water heater
      CORRECTION: Re-winterized it

```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WS     009114950003 -50 F GLYCERIN FREE BASE E-13977      3     9.34    28.02

```

```

*****
Job# Lab Code Description   LABOUR   Mech Bill to   Hrs   Rate   Total
*****
RI Z991  PREFORM ROOF INSPECTIO JL   I-PD      0.30  70.00  21.00
1 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
2 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
3 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
1 WARR  MANUFACTURER WARRANTY JL   W-1021    0.17  140.00  23.80
3 WARR  MANUFACTURER WARRANTY JL   W-1021    0.23  140.00  32.20
2 WARR  MANUFACTURER WARRANTY JL   W-1021    0.29  140.00  40.60
2 WARR  MANUFACTURER WARRANTY JL   W-1021    0.21  140.00  29.40
2 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
2 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
WS W495  WINTERIZE RV (WATER SY JL   E-13977   0.70  130.00  91.00
3 WARR  MANUFACTURER WARRANTY JL   W-1021    0.07  140.00  9.80
3 WARR  MANUFACTURER WARRANTY JL   W-1021    0.00  140.00  0.00
3 WARR  MANUFACTURER WARRANTY JL   W-1021    0.20  140.00  28.00

```

Continued on page 3

Work Order : 13182

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
WS  SSE      SHOP SUPPLIES - EXTERNAL  E-13977   1.00    6.83     6.83
WS  J-ADJ    QUOTE ADJUSTMENT          E-13977   1.00   -26.85   -26.85
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
E   13977          28.02     91.00     0.00    -20.02     5.47    104.47
I   PD              0.00     21.00     0.00     0.00     0.00     21.00
W   1021            0.00    163.80     0.00     0.00     0.00    163.80

Totals          28.02    275.80     0.00    -20.02     5.47    289.27
*****
```

&k2S
&k0S