



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65245

CUSTOMER WORK ORDER

WO #: 65245

Customer: 50801 - SCHERER, RANDY -
812-361-5369
Tag:
Author: BH
Location: IH

Stock #: 10810
Stock Desc: 2021 TT FOREST RIVER
CHEROKEE GREY WOLF 26DBH
Chassis #: 4X4TCKB23MK072684
Serial #: 4X4TCKB23MK072684
Mileage:
Licence:

Invoice #:
Date In: 15 SEP 21
Promised:
Date Sched:
Completed: 15 SEP 21
Warr. Date: 27 FEB 21

Job #1 - Warranty

COMPLAINT: CAMERA DOES NOT WORK INSIDE THE SUV DOES NOT WORK

CAUSE: CAMERA WILL REACH WHEN CLOSE BUT WONT REACH IN THE SUV

CORRECTION: CAMERA NEEDS TO BE REPLACED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	65.00

Parts

Part #	Description	Qty	Price	Total
732556	FURRION 5" REAR CAMERA SYSTEM	1.00	286.35	286.35

Subtotal for Job #1: 351.35

Parts Total:	286.35
Labour Total:	65.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	351.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Sep 2021



Customer #: 50801
SCHERER, RANDY



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	763582
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB23MK072684
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	017 / 017C
Labor rate:	\$130.00	ITEM #	CCKT26DBH
OWNER INFORMATION		DEALER RO #	65245
RANDY SCHERER		CLAIM START DATE	09/15/2021
2221 VOLKMAN RD		CLAIM END DATE	01/01/1900
Evansville, IN 47725			
USA			
Retail Date of Purchase	02/27/2021	WARRANTY EXPIRATION DATE	02/27/2022

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	40-196-01-00-001382	Back Up Camera - Electrical/12 Volt Interior/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2021-09-15 16:08:18 :: CAMERA DOES NOT WORK INSIDE T DOES NOT WORK CAMERA WILL REACH WHEN CLOSE BUT WONT REACH IN THE SUV NEED TO REPLACE T CAMERA				
	Model #	DRWC4.3M	Dlr Sub Hrs	0.50	Sub Labor Amt \$65.00
	Serial #	107L022027792684	Appr Hrs	0.50	Appr Labor Amt \$65.00

Notes

Submitted	Labor Amt	\$65.00	Approved	Labor Amt	\$65.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$65.00		Total	\$65.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	