

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2552159
<b>12024 CENTRAL AVE S.E.</b>		<b>CLAIM ORIGIN</b>	WEB
<b>ALBUQUERQUE, NM 87123</b>		<b>ORIGINAL CLAIM ID</b>	
<b>USA</b>		<b>VIN</b>	5ZT2AVRB3TB940730
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	050 / 050
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	AVT26DBS
<b>RAMON RAMOS</b>		<b>DEALER RO #</b>	71948
<b>12308 CLOUDVIEW AVE NE</b>		<b>CLAIM START DATE</b>	01/15/2026
<b>Albuquerque, NM 87123</b>		<b>CLAIM END DATE</b>	01/19/2026
<b>USA</b>			
<b>Retail Date of Purchase</b>	07/03/2025	<b>WARRANTY EXPIRATION DATE</b>	07/03/2026

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-01-00-001101	Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-01-15 12:14:49 :: Complaint: Large chip out of the trim on the slide above the couch Cause: Gouged trim Correction: Trim board will have to be replaced, 5 1/2 inches by 13 feet. Remove old trim and end caps. Nail new trim board and putty nail holes to replace end caps. Additional Note : stephanie@dealer-advisors.com, 2026-01-15 12:15:39 :: Previously approved on expired claim 2359114			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b>	\$95.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$95.00
	<b>Notes</b>			
	Changed to the correct code. Dp.			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>				
	F100684318	STILE, MM LVL SE. 18MM X 5-1/2 X 96, PRAIRIE BROWN, 47092122				
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>			
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$17.38	<b>Sub Freight</b>	\$185.78
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$17.38	<b>Appr Freight</b>	\$185.78
	<b>Notes</b>					

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>			
	20-46-01-00-000721	Window - Exterior/Windows/Replace/No Tread Code			
	<b>Complaint, Cause, Correction</b>				
	Original Note : stephanie@dealer-advisors.com, 2026-01-15 12:17:02 :: Complaint: Screw hole and hammer mark on kitchen window outside. Cause: Struck with a hammer and screw ran all the way through the window frame Correction: Removed old window and replace with a new window Previously approved on claim 2359114				
<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$190.00	
<b>Serial#</b>	<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b>	\$190.00	
	<b>Notes</b>				
	This is from expired claim #23549114. EXPIRED CLAIM GUIDELINES: The following guidelines have been created to assist our Warranty Departments in determining if the claim should be reviewed and/or processed for payment when it's been submitted after the original claim has expired. • The new claim must be submitted for authorization within 1 year of the original claim start date. Example: Claim start date is 12/21/2022. Dealer has unit 12/20/2023 to submit the new duplicate claim. • The Dealer must provide an explanation in the new duplicate claim as to why the original claim expired and why it is being submitted again. This should be stated in the				

Complaint, Cause, Correction box of the 1st labor line of the claim. • The new duplicate claim must have the original claim number in either the Dealer RO number or at the beginning of each Complaint, Cause, Correction box. • The new claim must contain all information and attachments that the original claim did. • The Dealer should attach a copy of the work order showing the actual repair dates. If no work order is provided and the unit is out of warranty, the repairs may be denied or adjusted. • If the repair was originally authorized by a Vendor, a new Vendor authorization may need to be obtained to ensure they are still willing to cover the repair or at least have been notified of the situation. •

Please attach all of the required information, picture(s) and documents to this claim. Thank you Dp.

The original claim expired because we were still working with Richard on a fix for the flooring. We still have not resolved this with him yet. We've been trying to get in touch with him. These two jobs on this claim are complete, but the flooring is not, so these were not submitted for payment. Work order is attached.

NVCB,.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

**Part**

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	F100106667	TRIM RING, 8505-7; 48.0 X 29.0; BLK 2442601, V000449629			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$18.33	<b>Sub Freight</b> \$0.00
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$16.62	<b>Appr Freight</b> \$0.00

**Notes**

Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5235198. The approved cost has been adjusted to \$14.45 + state allowed mark-up of 15%.

<b>Line# 2</b>	<b>Item #</b>	<b>Description</b>			
	F100747355	WINDOW, 8800, DW, 48 X 29, GLD TP BK, WINDOW, 8800, DW, 48 X 29, GLD TP BK, V001069701			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$149.10	<b>Sub Freight</b> \$185.78
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$129.65	<b>Appr Freight</b> \$185.78

**Notes**

<b>Submitted</b>	Labor Amt	\$285.00	<b>Approved</b>	Labor Amt	\$285.00
	Parts & Freight	\$536.92		Parts & Freight	\$535.21
	Total	\$821.92		Total	\$820.21

\_\_\_\_\_  
**DEALER** **DATE**  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.