



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65261

CUSTOMER WORK ORDER

WO #: 65261

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: DH
Location: 930CHECK WORK

Stock #: 10646
Stock Desc: 2022 TT COACHMEN
CATALINA 263BHCKLE
Chassis #: 5ZT2CARB3NU039464
Serial #: 5ZT2CARB3NU039464
Mileage:
Licence:

Invoice #:
Date In: 17 SEP 21
Promised:
Date Sched:
Completed: 24 SEP 21
Warr. Date:

Job #PDINTT - Internal
PDI - NEW TRAVEL TRAILER

Labor Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty
REMOTE FOR LED LIGHTS MISSING. NOTED
OMN DEL

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty
COMPLAINT: NO MARKER LIGHTS

CORRECTION: TOOK ALL LIGHTS OUT AND FOUND LEFT REAR SIDE LIGHT WAS SHORTED IN WALL, THE WIRE THAT GOES TO TOP LIGHT REAR STAPLE IN WALL SOME WHERE RAN NEW WIRE THROUGH REAR WALL AND THAT FIXED IT, HAD TO PUT ALL LIGHTS BACK TOGETHER AND RESEAL.

HELPED TRACK DOWN WIRING SHORT. FOUND THAT THE WIRING ON THE REAR LEFT CORNER HAD A GROUND SHORT IN THE WALL AND IT WAS FASTER TO REPLACE THE WIRE. WE UNHOOKED THE 12 VOLT POSITIVE WIRE THAT WAS GROUNDED IN THE WALL FROM THE LIGHT. RAN A NEW WIRE TO ONE OF THE LIGHTS FROM THE ELECTRICAL BOX UNDER THE TRAILER.

Labor Code	Description	Mechanic	Total
------------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Z990
Z990

MISC LABOUR CODE (EXTERNAL)
MISC LABOUR CODE (EXTERNAL)

DGH
GAH

390.00
390.00

Subtotal for Job #2: 780.00

Parts Total: 0.00
Labour Total: 780.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 780.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Sep 2021

W/O: 65261



Customer #: 1000
BASDENS AMERICAN RV,



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD

EVANSVILLE, IN 47725
USA

Labor rate: \$130.00

OWNER INFORMATION

Retail Date of Purchase

CLAIM STATUS Authorized
CLAIM 768065
CLAIM ORIGIN WEB

ORIGINAL CLAIM ID
VIN 5ZT2CARB3NU039464

CHASSIS VIN
MILEAGE 0

SITE/WAREHOUSE 103 / 103

ITEM # CAT263BHCKLE

DEALER RO # 65261

CLAIM START DATE 09/20/2021

CLAIM END DATE 01/01/1900

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code

40-106-24-11-001253

Operational Description

Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2021-09-20 11:16:35 :: NO MARKER LIGHTS MARKER LIGHTS BLOW FUSE WHEN HOOKED TO POWER, TOOK ALL LIGHTS OUT TO FIND OUT WHERE SHORT IS, FOUND LEFT REAR OUTSIDE LIGHT WIRE IS SHORTED IN WALL SOMEWHERE WOULD HAVE TO TAKE WALLS APART TO FIND.

Model #

Dlr Sub Hrs

8.00

Sub Labor Amt

\$1,040.00

Serial #

Appr Hrs

6.00

Appr Labor Amt

\$780.00

Notes

excessive Amount Requested

Submitted

Labor Amt	\$1,040.00
Parts & Freight	\$0.00
Total	\$1,040.00

Approved

Labor Amt	\$780.00
Parts & Freight	\$0.00
Total	\$780.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.