



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65269

CUSTOMER WORK ORDER

WO #: 65269

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0101EXTRA

Stock #: 10948
Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 260BH
Chassis #: 4YDTSG23N3101906
Serial #: 4YDTSG23N3101906
Mileage: 0
Licence:

Invoice #:
Date In: 17 SEP 21
Promised:
Date Sched:
Completed: 30 SEP 21
Warr. Date:

Job #BUNKHOUSE - Internal

COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE

CAUSE: BUNKHOUSE - PRE DELIVERY INSPECTION NEW BUNKHOUSE.

CORRECTION: Moved unit into shop from sales lot. Purged and filled LP tanks. Installed new battery box. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked roof and awning. Operated all electric stab jacks. Checked power cord. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked entrance door and all compartment doors. Made up winterizing hose. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked Radio. Recorded all serial numbers and took pictures. Checked TV antenna at all outlets with test TV. Filled fresh water tank and flushed antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 11 in.wc. Filled all holding tanks and checked monitor panel. Operated all appliances. Applied all company decals. Retracted all electric stab jacks. Drained all holding tanks, including water heater. Returned unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	8.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #1 - Warranty

COMPLAINT: DINETTE TABLE DOES NOT FIT ON POSTS

CAUSE: DINETTE TABLE DOES NOT FIT ON POSTS.

CORRECTION: Posts are mounted too close to wall and won't let table fit on posts. Post sockets on table need to be moved. Marked new socket location on table. Removed sockets from table. Moved to new location and remounted to table. Checked fit to table posts. Ok.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 65.00

Job #2 - Warranty

COMPLAINT: OUTSIDE SPRAY PORT MISSING (NOD)

CAUSE: OUTSIDE SPRAY PORT HOSE MISSING(NOD)

CORRECTION: 9/24/2021: Turned in parts request for a new hose. 9/29/2021: Received spray hose and placed in front compartment of unit.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	11.70
Z990	MISCELLANEOUS REPAIR	DKM	1.30

Parts

Part #	Description	Qty	Price	Total
201444	OUTSIDE SHOWER HOS	1.00	17.48	17.48

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SPRAY HOSE	1.00	12.54	12.54

Subtotal for Job #2: 43.02

Parts Total: 17.48
Labour Total: 78.00
Sublet Total: 0.00
Extras Total: 12.54
WORK ORDER TOTAL: 108.02

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 01 Oct 2021

W/O: 65269



Customer #: 1000
BASDEN'S AMERICAN RV,



e-Authorization

10/1/20
09:43:34

3-Authorization number PA02945857 Reference no: 65269 Status: Approved Approved by films
 Billing Name Address VIN Retail sold on
 34 Basden's American RV Basden's American RV 4YDTSGL23N3101906 Approved date 10/1/2021
 600 E Baseline Rd
 Evansville, IN 47725

Job operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3105018A Dinette Table - Fr	0.00	0.80	0.50		1	0.30	Complaint:DINETTE TABLE DOES NOT FIT ON POSTS Cause:DINETTE TABLE DOES NOT FIT ON POSTS. Correction:Posts are mounted too close to wall and won't let table fit on posts. Post sockets on table need to be moved. Marked new socket location on table. Removed sockets from table. Moved to new location and remounted to table. Checked fit to table posts. Ok. KRV - Labor time approved in accordance with Keystone RV's flat rate manual.
2	6201224A Rubber Hose - Re	0.00	0.10	0.10		1	0.10	Complaint:OUTSIDE SPRAY PORT MISSING (NOD) Cause:OUTSIDE SPRAY PORT HOSE MISSING(NOD) Correction:9/24/2021: Turned in parts request for a new hose. 9/29/2021: Received spray hose and placed in front compartment of unit.

3-Authorization number PA02945857 0.60

For paper claims only use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the