



Pre-Authorization

Pre-Authorization number	PREAUTH102051 (PA03993262)	Reference no.79642	Status	Approved
--------------------------	-------------------------------	--------------------	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd
Evansville, IN 47725 VIN 4YDTSGL23S7103014 Retail sold on

Root		Approved		Actual	Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
5101906A	Light, Clearance & Taillight - Repair	0	0.4	0.4		1	Complaint: RUNNING LIGHT IS OUT OFF DOOR FRONT TOP. Cause: Off door side top front running light doesn't work Correction: On my inspection of the lights i found that this one didn't work. I tested the wires and i had power there. So i replaced the the light and it works properly now. I put budle tape on the backside where the screws go through and i sealed up the outside with clear silicone. Good to go
6103508B	Pump - Replace	0	0.3	0.3		1	Complaint: WATER PUMP WILL NOT KEEP PRESSURE TRIED TO ADJUST WILL NOT ADJUST Cause: Water pump does work properly Correction: The factory water pump ran and shut off. Didn't stay running the whole time when i had the faucet open and it made the water heater not work properly. We tried to adjust the factory pump but it didn't help. So i installed a new water pump. It works properly and water heater works properly. No leaks. Good to go
Pre-Authorization number: PREAUTH102051				0.7			

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.