



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26790
Promised Date:



WO #: 26790 (Appointment Date: 30 MAR 2026 - Time: 10:00am)

Customer: 92180 - BOURGEOIS, KIRK
Address: 127 CHIPMUNK HOLLOW WAY
NEWPORT, TN
37821

Home Phone: (423) 237-8828

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11106
Stock Desc: (11106) 2025 FOREST RIVER
SANDPIPER 3900HBLR
Model: 3900HBLR
Serial #: 4X4FSAR28SJ048285
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 26 SEP 25
Date In: 04 MAR 26
Promise Date: 30 MAR 26
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date: 26 SEP 25

Job #1 - External

SC TO TURTLE ROCK LOT 102 (TRY)
100.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR LEAKING AT VERY BOTTOM
NEED PROOF OF LEAK, AND DOOR TAG

CAUSE: TECH FOUND THE ENTRY DOOR NOT CLOSING ALL THE WAY AND LEAVING A GAP IN DOOR.

CORRECTION: ADJUST ENTRY DOOR TO CORRECT POSITION
LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

BLACK TANK #2 HANDLE IS BENT

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DS BIG COMPARTMENT DOOR LEAKING AND ALLOWING WATER TO ENTER THE COMPARTMENT AREA

CAUSE: RUBBER DOOR SEAL DAMAGED FROM THE LOCK STRIKER, THIS IS ALLOWING WATER IN THE COMPARTMENT AREA.

CORRECTION: REMOVE CURRENT COMPARTMENT DOOR SEAL, CLEAN AREA, REPLACE WITH NEW SEAL AND WATER TEST. NEED TO ADJUST LOCK TO PREVENT NEW SEAL FROM BEING DAMAGED AGAIN.
LABOR .75

Customer #: 92180
BOURGEOIS, KIRK





Subtotal for Job #4: 0.00

Job #5 - Warranty

PHOTO OF THE CEILING TRIM THAT WAS FIXED PRIOR

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUST REMOVED STICKER PUT ON AT THE FACTORY AND PEELED THE DOOR PAPER OFF

CAUSE: FACTORY PUT A STICKER ON THE BATHROOM DOOR AND WHEN CUST REMOVED IT THE DOOR OVERLAY PEELED OFF

CORRECTION: REMOVE AND REPLACE THE BATHROOM DOOR
LABOR .50

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: LOWER FRIDGE DOOR IS DRAGGING
PLEASE GET THE TAG SERIAL AND MODEL BOTH (JPS)

CAUSE: LEFT SIDE FRIDGE DOOR IS HANGING CROOKED AND NOT CLOSING PROPERLY

CORRECTION: NEED DOOR INSERTS AND LOWER ARM TO CORRECT CONCERN
LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: SMALL DRESSER DRAWERS IN BEDROOM WILL NOT CLOSE

CAUSE: ALL THE DRAWERS IN THE SMALL DRESSER WILL NOT CLOSE CORRECTLY
TRACKS AND RAILS ARE MISSING BEARINGS AND THE SCREW HOLES ARE STRIPPED OUT

CORRECTION:
NEED TO REPLACE ALL HARDWARE ON ALL 4 DRAWERS
LABOR ON ALL 4: 2.0

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: ONE BLIND IN LIVING AREA AT SEATING HAS A PIN HOLE THAT HAS DEVELOPED
WILL NEED THE TAG ON THE TOP OF THE SHADE

CAUSE: A SMALL PIN HOLE HAS DEVELOPED ON THE MATERIAL OF THE SHADE, MATERIAL IS
VERY THIN IN THIS AREA. FAULTY MATERIAL

CORRECTION: REMOVE CURRENT SHADE AND REPLACE WITH NEW ONE
LABOR .50

Subtotal for Job #9: 0.00

Job #10 - Warranty

NEED THE TAG PHOTO AND OVERALL OF BLIND THAT WAS ADJUSTED



Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: TOILET IS LEAKING WILL NEED CLEAR PHOTO OF TAG
CUST SAID IT WAS OVER FLOWING

CAUSE: WATER VALVE IS NOT CLOSING ALL THE WAY AND ALLOWING A SMALL TRICKLE OF
WATER TO PASS THROUGH
THIS IS CAUSING THE TOILET TO EVENTUALLY OVER FILL

CORRECTION: REMOVE AND REPLACE WATER VALVE TO CORRECT ISSUE, THEN TEST
LABOR WITH DIAG .75

Subtotal for Job #11: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 01 Apr 2026

W/O: 26790
Promised Date: 30 MAR 26



Customer #: 92180
BOURGEOIS, KIRK

