

Dealership: **Tri-AM RV Center of East TN** 423-235-1167

Origin : **Indiana**

VIN: **TD431652**

Brand: **Bullet**

Model: **BL2530RD26**

"SUBJECT TO FURTHER INSPECTION" DOES NOT APPLY TO TRANSPORTATION DAMAGE!

- DAF is to document possible damage and missing equipment, not normal warranty defects.
- While the driver is present, list the specific location of any of the below questions answered "YES". Keystone will make the determination if the issue is related to the driver transportation.

Keystone shipped units:

- Dealers-No need to e-mail/fax the DAF, the transport driver is required to return the original to Keystone/Dutchmen/CrossRoads

Driver Pick-up (DPU):

- Obvious exterior damage(s) should be reported to the Shipping Department at the time of factory picked-up
- Within 24 hours of receiving the unit at the dealer location, complete the DAF and e-mail to daf@keystonerv.com

Exterior	Yes	No	Location
Evidence of impact/drag on walls/wall components/caps/graphics/paint			
Evidence of impact/drag to rubber roof, roof components or awning			
Evidence of impact/damage/road debris to axles/suspension/underbelly			

Interior	Yes	No	Location
Obvious torn/cut/punctured/stained furniture			
Obvious dinged/dented/scratched TV/Appliance doors/face's/trims			
Obvious torn/cut/punctured/stained carpet/Linoleum			
Obvious dinged/dented/scratched doors/cabinet front's	X		① Cabinets over bed have 2 spots where paints scratched ③ Blk trim has paint on it above exit door
Equipment listed on Invoice is on the unit			
Missing items/equipment outside/inside			

Comments: ② Rear light strips on (R) & (L) side not working
 ④ Bedroom door has 2 scratches ⑤ Kitchen cabinet over sink touching, not closing all the way.

Dealer Rep Signature: Cole Perkins Printed: Cole Perkins Date: 3/10/26
 Driver Signature: Steve Thompson Printed: Steve Thompson Date: 2/10/26

4YDTBLM26TD431652

