



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73140  
 Promised Date:  
 10 APR 26



WO #: 73140 (Appointment Date: 02 APR 2026 - Time: 08:45am)  
 Customer Name: 59966 - HUMPHREYS, CHRISTOPHER SEAN  
 Completed Date:  
 Invoice#:  
 Author: ADVISOR  
 Stock Desc: 9374 2024 R-POD RP-196  
 Serial#: 5ZT2RPJC1RV025973  
 Chassis#: 5ZT2RPJC1RV025973  
 Miles/Hrs:  
 Tag#: 7142  
 Purchased Date: 29 MAY 25  
 Warranty Date: 29 MAY 25  
 Date In: 02 APR 26  
 Time In:

**Job #1 - Warranty**

COMPLAINT: CUSTOMER STATES WHEN USING BLACK WATER FLUSH WATER COMES OUT FROM UNDER UNIT \*\*UNDER WHERE THE BLACK TANK FLUSH IS & OTHER SIDE UNDER WHERE THE WASTE WATER HOLDING TANK IS\*\*

CAUSE: CUSTOMER REQUESTED we check out the black tank flush and black tank because it sometimes is leaking on the grey tank side

CORRECTION: Filled up black tank all the way until standing water in toilet. filling up gray tank currently to check for leaks. Determined that shower is leaking at the drain underneath the shower. Upon taking it to be dumped a bunch of water built up in the under belly padding from the leaking shower, directly in the spot that the customer stated. Need 1.5 hour to repair.

**Labor**

Job #	Description	Total
1	BLACK TANK FLUSH	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: CUSTOMER STATES WHEN USING BLACK WATER FLUSH WATER ALSO COMES OUT FROM ONE OF THE WALLS INSIDE UNIT \*\*KIND OF WHERE THE WALL BEGINS TO GO ROUND - MAY BE COMING OUT AT THE TOILET AREA\*\*

CAUSE: ISSUE CAUSED BY the Back flow preventer check valve for the Black tank flush is leaking profusely

CORRECTION: The check valve needs to be replaced. Model 571 125 psi half inch. We will need 30 minutes to replace it

**Labor**

Job #	Description	Total
2	BLACK TANK FLUSH	N/C

Customer #: 59966  
 HUMPHREYS,  
 CHRISTOPHER SEAN





**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: CUSTOMER STATES CABINET DOOR ABOVE KITCHEN SINK IS BROKE \*\*HINGE BROKE OFF DOOR\*\*

CAUSE: ISSUE CAUSED BY The bouncing of the trailer has caused the screw holes to strip it has been tried to hook in the same place multiple times

CORRECTION: Recommend moving the piston to the other side of the door using proper screws to secure. Requesting .25

**Labor**

Job #	Description	Total
3	CABINET DOOR	N/C

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: CUSTOMER STATES REFRIGERATOR IS NOT STAYING COLD ON LP - WORKS WHEN ON SHORE POWER

CAUSE: ISSUE CAUSED BY Propane regulator

CORRECTION: I was able to get the fridge to ignite and start cooling from a different line I determined that the regulator needs to be replaced. Requesting 30 minutes to verify that its working after regulator is replaced. When I was first trying to start it up in propane mode there was a red light indicating that propane mode was not working but then it started after I attempted to relight pilot second time

**Labor**

Job #	Description	Total
4	REFRIGERATOR DIAGNOSTIC TIME	N/C

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: CUSTOMER STATES STOVE STOP BURNERS NOT STAYING LIT

CAUSE: ISSUE CAUSED BY Regulator is running at 9 needs to be 11

CORRECTION: Regulator needs to be replaced on unit Requesting 30 minutes. Single stage

**Labor**

Job #	Description	Total
5	STOVE TOP DIAGNOSE	N/C

**Subtotal for Job #5: 0.00**

**Job #NOTE - External**

CUSTOMER STATES UNIT IS NOT WINTERIZED & WHEN HE PICKED UNIT UP HE NEVER RECEIVED HOSE FOR VACUUM

**Subtotal for Job #NOTE: 0.00**

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**



NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 08 Apr 2026

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 73140  
Promised Date: 10 APR 26



Customer #: 59966  
HUMPHREYS,  
CHRISTOPHER SEAN

