



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65439
Promised Date: 30 OCT 21

CUSTOMER WORK ORDER

WO #: 65439

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: DH
Location: 1022 CHECK PREAUTH

Stock #: 10706
Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 266RL
Chassis #: 4YDTSG2XN3102213
Serial #: 4YDTSG2XN3102213
Mileage: 0
Licence:

Invoice #:
Date In: 06 OCT 21
Promised: 30 OCT 21
Date Sched:
Completed: 22 OCT 21
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: J WRAP AT CURB SIDE CORNER LOOSE

CAUSE: J WRAP AT CURBSIDE REAR CORNER LOOSE.

CORRECTION: Screws that factory installed "J" wrap with pulled out. Repositioned "J" wrap at curbside rear corner and reattached with new screws.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	39.00

Subtotal for Job #1: 39.00

Job #2 - Warranty

COMPLAINT: MANUAL CRANK MISSING FOR ELECTRIC JACK

CAUSE: MANUAL CRANK MISSING FOR ELECTRIC JACKS.

CORRECTION: 10/18/2021: Received new crank for electric jacks. Plased new crank in front compartment of unit.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	13.00



Customer #: 1000
BASDEN'S AMERICAN RV,

W/O: 65439
Promised Date: 30 OCT 21

Parts

Part #	Description	Qty	Price	Total
BRV102885	JACK - CRANK HANDL	1.00	10.60	10.60

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CRANK HANDLE	1.00	24.41	24.41

Subtotal for Job #2: 48.01

Parts Total: 10.60
Labour Total: 52.00
Sublet Total: 0.00
Extras Total: 24.41
WORK ORDER TOTAL: 87.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Oct 2021

Customer #: 1000
BASDENS AMERICAN RV,



Pre-Authorization

10/22/20
06:42:08 PM

Approved date 10/21/2021

Approved by flins
Retail sold on

Status: Approved
VIN

Reference no: 65439
Address

Authorization number PA02962040
Name
aler

4YDTSGL2XN3102213

Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

Basden's American RV

Ju Root Description Sublet Sub hours Approved hours Actual hours Qty Base hours Complaint / Cause / Correction

1 2101316A Metal Lower Wrap 0.00 0.30 0.30 1 0.50 Complaint: J WRAP AT CURB SIDE CORNER LOOSE
Cause: J WRAP AT CURBSIDE REAR CORNER LOOSE.
Correction: Screws that factory installed "J" wrap with pulled out.
Repositioned "J" wrap at curbside rear corner and reattached with new screws.

2 1210324B Stabilizer Jack - F 0.00 0.10 0.10 1 0.10 Complaint: MANUAL CRANK MISSING FOR ELECTRIC JACK
Cause: MANUAL CRANK MISSING FOR ELECTRIC JACKS.
Correction: 10/18/2021: Received new crank for electric jacks.
Placed new crank in front compartment of unit.

Authorization number PA02962040

0.40

For paper claims only use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the