

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79890
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 54437 - RONALD WHITTENBURG
Address: 10501 DRIVER DRIVE EVANSVILLE, IN

47725

Phone: 573-429-9330

Stock Number: 11745 - 2026 COUGAR HALF-TON 28RLI 4YDFCGN22T2506164

VIN: 4YDFCGN22T2506164 HIN: SER#: 4YDFCGN22T2506164

Mileage: 0 Work Order Comp: 29 MAY 26

Auth. No: Dealer #: 1194

Warr. Date: 31 MAR 26 Work Order Date: 11 MAY 26 Inv #: 430702

WO # Job # Description JOB INFORMATION

79890 3 CHECK THE REMOTE WITH THE A/C NOT CHANGING THE TEMP
Plugged in the shore power then got the ac remote to power on the
ac but the remote didn't respond to the ac. Manually pushed the
power button on the ac to power on. Set the temp on the remote
but the ac didn't respond. Set the temp manually then tried again
with the remote and the remote changed the temp but only after
manually changing. Called lippert to discuss the ac and remote.
They recommended a remote replacement. Put in a parts request.
CUSOTMER PICKED UP PARTS AND WORKS FINE

79890 1 OFF DOOR SIDE REAR SLIDE HAS A RUBBING GRINDING NOISE EVERYONCE
IN A WHILE See been on noise coming from off door side tire area
from the outside
Lubrication
Had BEN run the slideroom out and in 6 times and only once heard
the squeak. With the slideroom out sprayed slide lubricant all
over the mechanism.

79890 4 STORAGE DOOR ON THE DS FRONT IS CROOKEDneeds adjust
Compartment door crooked
Took pictures of the crooked door the cut the silicone and
unscrewed the door from the body. Pushed the door towards the
back then put the screws back in. Trimmed with silicone. Took
pictures of the process.

Part No	Job#	Description	PARTS	Qty	Price	Total
779541	3	A/C - Ceiling Assembly - Remote O		1.00	40.39	40.39

Date: _____