

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65545

Completed : 19 NOV 21 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10788 Description : 2021 5W KEYSTONE MONTANA 3121RL
Tag : Date In : 20 OCT 21 Mileage : 0
Author : BH Promised :
Location : 1120 CHECK PREAUTH Date Sched :
Serial# : 4YDF31229M4702545 Chassis# : 4YDF31229M4702545
Warr. Date : 26 FEB 21 Cust PO# :
Print Date : 19 NOV 21

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: SHOWER DOOR BY THE RUBBER PIECE LOOSE W 1013 KEYST
HANDLE
CORRECTION: REMOVED THE HANDLES AND BENT BACK IN
SHAPE TO HOLD TO THE GLASS AND PUT BACK
ON.
2 COMPLAINT: TRIM OFF BATHROOM DOOR TRIM ON THE DOORS W 1013 KEYST
THE TRIM IS ON THE BED
CORRECTION: INSTALLED NEW DOOR IN THE BATHROOM.
3 COMPLAINT: KITCHEN TABLE TOP BROKE IT IS ON THE BED I SPN SALES
CORRECTION: INSTALLED NEW TABLE TOP.
4 COMPLAINT: BED ROOM DOOR CATCHES I SPN SALES
CORRECTION: LUBRICATED THE ROLLERS AND OPERATED
DOOR SEEMED TO WORK FINE. THERE IS A
MAGNET ON TOP OF THE DOOR TO HOLD IT
OPEN,
5 COMPLAINT: FRIDGE DOOR LATCH DOES NOT GO ALL THE I SPN SALES
WAY IN (CUSTOMER WANTS TO KNOW HOW TO
SHUT THE FRIDGE OFF ALSO)
CORRECTION: KNW IS ONLY TO KEEP DOORS FROM SWINGING
OPEN AND IF THE FREEZER BUTTON AND THE
FRIDGE BUTTON ARE HELD AT THE SAME TIME
THE FRIDGE SHUTS OFF THE COOLING
PROCESS.
6 COMPLAINT: PANTRY PANEL AT THE BOTTOM OFF W 1013 KEYST
CORRECTION: INSTALLED NEW SCREWS.
7 COMPLAINT: HYDRAULIC LEAK LEFT FRONT AUTO LEVELING W 1013 KEYST
BOX LINES SEE BEN
CORRECTION: INSTALLED NEW HYDRAULIC LINE AND
CHECKED FOR LEAKS.
8 COMPLAINT: LIGHT BULB FIXTURE OVER ISLAND IT IS IN E 50854 MAXWE
THE SINK
CORRECTION: CUSTOMER GOING TO GET OWN BULBS.
9 COMPLAINT: TRIM OFF IN LIVING ROOM ABOVE LOVESEAT W 1013 KEYST

Continued on page 2

Work Order : 65545

```

*****
Job #   Description                      JOB INFORMATION                      Type Bill To
*****
                                CLEAN IT GOES TO THE TOP PIECE OF THE
                                JOINT INBETWEEN THE SHADES
10      CORRECTION: secured the crown molding with nails.
      COMPLAINT: CHECK WATER HEATER MAKE SURE IT IS          E      50854  MAXWE
                                WORKING CUSTOMER LEFT IT ON
      CORRECTION: I TURNED ON WATER HEATER AND RESET THE
                                LIMIT SWITCH  AND LET RUN  THE WATER
WINT     COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.  E      50854  MAXWE
                                ***INCLUDES 2 GALLONS OF ANTI-FREEZE***
                                UNITS WITH WASHING MACHINE OR ICEMAKER
                                WILL BE EXTRA **DE-WINTERIZATION IS NOT
                                INCLUDED**
      CORRECTION: WINTERIZED UNIT AND DRAINED LINES.

```

```

*****
Job # Part No Description          PARTS          Bill to      Qty      Price      Total
*****
2      638928 Passage - Door - 1          W-1013          1      148.75     148.75
3      655452 DINETTE TABLE 26 x          I-SPN           1      262.90     262.90
WINTE 24181  -50 RV ANTI-FREEZE GALLON          E-50854         0        4.49        0.00
WINTE 6385   FILTER BYPASS KIT              E-50854         1      60.99     60.99

```

```

*****
Job# Lab Code Description          LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.50     130.00     65.00
2 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.01     130.00        1.30
2 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.39     130.00     50.70
3 Z990 MISCELLANEOUS REPAIR          BRM I-SPN           0.09      25.00        2.25
3 Z990 MISCELLANEOUS REPAIR          BRM I-SPN           0.41      25.00     10.25
4 Z990 MISCELLANEOUS REPAIR          BRM I-SPN           0.10      25.00        2.50
5 Z990 MISCELLANEOUS REPAIR          BRM I-SPN           0.35      25.00        8.75
6 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.20     130.00     26.00
7 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.50     130.00     65.00
7 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.50     130.00     65.00
7 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.00     130.00        0.00
8 Z990 MISCELLANEOUS REPAIR          BRM E-50854         0.00     130.00        0.00
8 Z990 MISCELLANEOUS REPAIR          BRM E-50854         0.00     130.00        0.00
9 Z990 MISCELLANEOUS REPAIR          BRM W-1013          0.30     130.00     39.00
10 Z990 MISC LABOUR CODE (EXTE BRM E-50854          0.50     130.00     65.00
INTER Z990 WINTERIZE UNIT              BRM E-50854         0.00     130.00        0.00
INTER Z990 WINTERIZE UNIT              BRM E-50854         1.00     130.00    130.00

```

```

*****
Job # Excode Description          EXTRAS          bill to      Qty      Price      Total
*****
2 FRT CRATE - JOBS 2,3          W-1013          1.00     50.00     50.00
3 FRT FREIGHT - JOBS 2,3          I-SPN           1.00     91.45     91.45

```

Continued on page 3

Work Order : 65545

```

*****
Job #  Excode   Description  EXTRAS      bill to      Qty      Price      Total
*****
INTER  SS       SHOP SUPPLIES      E-50854      1.00       9.70       9.70
    7  PARTS     HYDRAULIC LINE      W-1013      1.00      44.85      44.85
*****

```

 CUSTOMER COMMENTS

BH SENT PREAUTH TO MATT11-19
 BH GOT APPROVEL FROM KEYSTONE 11-19
 BH SENT IN PREAUTH WAITING TO HEAR BACK 11-18
 DOOR AND TABLE IN SHOP 1A 10-28-21...CAM
 ORDERED FILTER BYPASS KIT PER BEN. 10-25-21
 INFORMED BEN THAT LIGHT BULBS ARE NEVER WARRANTY. CUSTOMER WILL
 SOURCE ON HIS OWN,
 ORDERED DOOR AND DINETTE TABLE PER BEN 10-25-21.

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	50854	60.99	195.00	0.00	9.70	4.95	270.64
I	SPN	262.90	23.75	0.00	91.45	24.80	402.90
W	1013	148.75	312.00	0.00	94.85	0.00	555.60
Totals		472.64	530.75	0.00	196.00	29.75	1,229.14