



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27120
 Promised Date: 06 MAY 26



WO #: 27120

Customer: 72736 - HICKMAN, MARK
 Address: 3103 MARCUM DR
 MORRISTOWN, TN
 37814

Home Phone: (423) 273-0005

Work Phone:

Author: SPD

Location: TET

Invoice #:

Stock #: 10879

Stock Desc: 2024 FW FOREST RIVER CEDAR

CREEK 371FL

Model: 371FL

Serial #: 4X4FCRN25RS232718

Chassis #:

Mileage: 0

Key #: 9500

Req'n #:

License #:

Trim:

Purchase Date: 06 JUN 24

Date In: 06 MAY 26

Promise Date: 30 MAY 26

Promise Time:

Schedule Date:

Completed: 27 MAY 26

Warr. Date: 06 JUN 24

Job #1 - Warranty

COMPLAINT: CS THAT THE FRIDGE IS NOT COOLING ON THE FRIDGE SIDE BUT THE FREEZER FEELS COOL (FOUND PINK ICE IN TRAY) SO NOT SURE WHATS GOING ON UNIT CONTROLS LIGHT UP BUT NO LIGHTS ON THE INSIDE

CAUSE: TECH ALLOWED OVER 8 HOURS FOR COOL DOWN TIME TO FIND FREEZER WAS 20 DEGREES AND FRIDGE WAS 68. VOLTAGE AMP CAME BACK GOOD AT 14.3 VDC, AMPS ARE LOW AT 4.3. ALSO VERIFIED INTERIOR LIGHT IS INOP

CORRECTION: REMOVE CURRENT FRIDGE AND REPLACE WITH NEW ONE TO CORRECT ISSUES REPLACE FRIDGE LABOR AND DIAG .70

Labor

Job #	Description	Hours	Total
1	REPLACED BOARD	0.70	122.50

Parts

Part #	Description	Qty	Price	Total
F100722320	REFRIGERATOR, PART, MAIN CONTROL PANEL/BOARD, GENERATION 2.0, REPLACEMENT FOR FURRION FCR20DCAFA [GA10] V#2025014800 (9A-SOP)	1.00	295.99	295.99

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	27.38	27.38

Subtotal for Job #1: 445.87

Parts Total: 295.99
 Labour Total: 122.50
 Sublet Total: 0.00
 Extras Total: 27.38
WORK ORDER TOTAL: 445.87

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 72736
 HICKMAN, MARK



Customer Signature : _____

Date: 27 May 2026

W/O: 27120
Promised Date: 30 MAY 26



Customer #: 72736
HICKMAN, MARK



Customer Work
Order

