



Claim CLAIM106238 (C3949289) Last Modified By

										Changed	
Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	warranty rate	Type	Date of Purchase
CLAIM106238 (C3949289)	40500	4/28/2026	5/3/2026	4YDFAVU2XTE760487	PA03995917	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970

Deny code	Item number	Name	Quantity	Returned	Dealer price	Part Markup	Appr total	Sub Freight	Sublet	Status
96	693619	A/C - Shroud Only - 15.0 BTU - Power Saver - Quiet Series - Polished Black	1	0	279.89	30.00	363.86	55.80	55.80	0.00 Approved

Inv 5169093 Component Model 1 Component Serial Number 1

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4157106A	A/C - Furrion - Repair	0.8	0.8	132	0	1	0.5	Approved
Complaint Dealer states that the AC cover is not put together correctly, the seams are overlapping. Cause Hurried assembly at the manufacturer. Correction AC cover was cross lapped where the 2 plastic cover pieces should join each other. Unscrewed cover, realigned, functions as it should but it will not line up correctly. It is not cosmetically pleasing for a new high end unit, recommend new cover. KRV- Approved as Goodwill to replace Cover									

Submitted parts & subLet	363.86	Approved parts & subLet	363.86
Submitted labor & subLet	132.00	Approved labor & subLet	132.00
Submitted freight	55.80	Approved freight	55.80
Total Submitted	551.66	Total approved	551.66