



Claim CLAIM102247 (C3945365) Last Modified By

										Changed		
Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	warranty rate	Type	Date of Purchase	
CLAIM102247 (C3945365)	40538	4/30/2026	4/30/2026	4YDFAVR27TE760410	PA03995432	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	5/8/2026	

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6102102A	Fresh Water Tank - Below Floor - Fill Hose	1	1	165	0	1	0.5	Approved
Complaint Customer states that the fresh water tank valve won't close. Cause Gate valve cable is bent and not allowing the valve to travel in and out. Correction When trying to fill the fresh tank, I found the gate valve was stuck open, when I pulled the cable valve system out of the underbelly and found the cable at the valve was bent and not allowing itself to travel back and forth in the plastic tubing that is around the cable. Being that the valve is already on the outside of the underbelly, I removed the cable and turned the valve so the handle would face the side of the camper.									

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	165.00	Approved labor & subLet	165.00
Submitted freight	0.00	Approved freight	0.00
Total Submitted	165.00	Total approved	165.00