



Claim CLAIM108328 (C3951352)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed		Date of Purchase
									warranty rate	Type	
CLAIM108328 (C3951352)	40651	5/12/2026	5/14/2026	4YDTATU24T8920417	PA04000800	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	5/2/2026

Deny code	Item number	Name	Qty	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	211116	Warranty Shop Supply - Plumbing Fittings and Pipe	1	0	10.00	30.00	13.00	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6100706A	Drain Lines - Waste - Repair	2.3	2.3	379.5	0	1	0.2	Approved
		Complaint Customer states the sewer drain pipe is sloped upward and does not drain properly. Cause Drain line is not installed properly and doesn't drain because of it. Correction Cut 3" and 1.5" pipes, added 3" and 1.5" couplers, turned elbow down to slight grade downward. Pipe now drains properly. This was a service call to the customers location, time reflects working outside of shop environment which is why it took a little longer.							
		Notes not duplicate			379.5				

Submitted parts & subLet	13.00	Approved parts & subLet	13.00
Submitted labor & subLet	379.50	Approved labor & subLet	379.50
Submitted freight	0.00	Approved freight	0.00
Total Submitted	<u>392.50</u>	Total approved	<u>392.50</u>