



Claim CLAIM107799 (C3950821)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed		Date of Purchase
									warranty rate	Type	
CLAIM107799 (C3950821)	40666	5/14/2026	5/15/2026	4YDFARP23TE550154	PA04001408	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	5/15/2026

Deny code	Item number	Name	Quantity	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	211107	Warranty Shop Supply - Adhesive and Adhesive Tape	1	0	3.00	30.00	3.90	0.00	0.00	0.00	Approved
90	102107	Sealant - Silicone - Neutral Cure - Translucent - (30/Case)	1	0	3.00	30.00	3.90	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5102816A	Light, LED-Striplight	0.3	0.3	49.5	0	1	0.3	Approved
	<b>Complaint</b> Dealer states the LED lights on nose cone are falling off.				<b>Notes</b> Stock				
	<b>Cause</b> Adhesive failure.				49.5				
	<b>Correction</b> Cleaned the track where the light lay, then put 3M double sided tape down and laid light strip back in place and sealed the stop with clear caulk.								

<b>Submitted parts &amp; subLet</b>	7.80	<b>Approved parts &amp; subLet</b>	7.80
<b>Submitted labor &amp; subLet</b>	49.50	<b>Approved labor &amp; subLet</b>	49.50
<b>Submitted freight</b>	0.00	<b>Approved freight</b>	0.00
<b>Total Submitted</b>	<u>57.30</u>	<b>Total approved</b>	<u>57.30</u>