

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #		1054928	CLAIM STATUS		Paid
LINK FORD & RV MINONG LLC			CLAIM		2684944
1025 W HOKAH ST			CLAIM ORIGIN		WEB
MINONG, WI 54859			ORIGINAL CLAIM ID		
USA			VIN		5ZT2TRNB8TB526916
			CHASSIS VIN		
			MILEAGE		0
Labor rate:	\$165.00		SITE/WAREHOUSE		048 / 048B
OWNER INFORMATION			ITEM #		TRT235RK
JOSEPH BAILEY			DEALER RO #		40668
9475 JARDINE RD			CLAIM START DATE		05/22/2026
Port Wing, WI 54865			CLAIM END DATE		05/26/2026
USA					
Retail Date of Purchase		04/30/2026	WARRANTY EXPIRATION DATE		04/30/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : alix@dealer-advisors.com, 2026-05-22 10:55:43 :: Complaint: Customer states that there is water leaking in the underbelly right next to the water heater. Customer also found that the kitchen sink p-trap is not hooked up at all. Cause: Plumbing under kitchen sink not connected. Correction: Checked P trap, found the 45 coming from vent pipe was not glued to tail pipe or vent pipe all was loose. Glued 45 to vent pipe, cut new section of pipe, glued and installed. Then glued and installed coupler to connect pipes, adjusted tail pipe and trap on sink to line up and installed, tightened all fittings, tested with water, found no leaks. Tested with water, checked the underbelly and found no leaks by water heater. Also checked plumbing under bathroom sink, was loose, tightened fittings. Also removed panel and checked water lines from sink to water heater and found no leaks there.				
	Model#	Dlr Sub Hrs	2.30	Sub Labor Amt	\$379.50
	Serial#	Appr Hrs	2.30	Appr Labor Amt	\$379.50

Notes

Please provide photo's that depict the concern described in the Complaint, Cause, and Correction notes. Please provide pictures of the following: Leak described at the underbelly. The complaint it what the customer stated. The tech checked for water leaks under there and found none after fixing the items listed in the correction. Everything the tech found/fixed is depicted in the photos. The complaint is suppose to be what the customer is stating, so I am not sure how to provide photos when the correction clearly states we saw no leaks in underbelly after fixing the items states. Thanks.

NVCB 2.30 to connect the drainage line under the sink due to it being loose. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1	Item #		Description			
	USERPART		Shop supplies - 1-1/2 in 45 ABS elbow, CPLG 1 1/2, glue			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$18.98	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$18.98	Appr Freight	\$0.00

Notes

Submitted		Labor Amt	\$379.50	Approved		Labor Amt	\$379.50
		Parts & Freight	\$18.98			Parts & Freight	\$18.98
		Total	\$398.48			Total	\$398.48

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.