



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE ALPINE  
4YDFAVU2XTE760487  
1 Mi In  
Stock #: KS26-33

**Service Advisor**  
KEVIN GOODIEL  
goodielk

<b>A. MISCELLANEOUS</b>	<b>DEALER STATES THAT THERES LAP SEALANT ON AC ON THE ROOF, AND THERES LAP SEALANT ON TOP OF NOSE CONE</b>	<b>Warranty Pay</b>	<b>\$165.00</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Sloppy caulk job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.69	1	1	\$165.00	\$24.00

1. Scraped caulk off with plastic scraper on both the nose cone and ac cover. Cleaned them both off with light cleaner. requested 1 hour

<b>Total Labor Sale</b> \$165.00	<b>Total Labor Cost</b> \$24.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>B. MISCELLANEOUS</b>	<b>DEALER STATES THAT THE AC COVER IS NOT PUT TOGETHER CORRECTLY THE SEAMS ARE OVERLAPING EACH OTHER</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Hurried assembly





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50  
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.23	0.3	0.3	\$49.50	\$7.20

1. Ac cover was cross lapped where the 2 plastic cover pieces should join each other. Unscrewed cover, realigned. Functions as it should. Not cosmetically pleasing for a new high end unit. Recommend new cover. requested .5

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$7.20	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>C. MISCELLANEOUS</b>	<b>DEALER STATES DEALER STATES THAT THE OFF KITCHEN SLIDE OUT VINYL IS KINKED LIKE MAYBE THE FACIA BOARDS ARE NOT CUT SHORT ENOUGH</b>	<b>Warranty Pay</b>	<b>\$99.00</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Board behind trim molding was loose. Vinyl was unattached behind trim. Removed trim molding. Removed old nails. Scraped off glue. Tightened screws on backboard. Added extra screw for extra strength. Straightened and stapled vinyl to support board to fix kink in vinyl. Reattached trim. Cleaned up. requested.6 hours

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00  
Labor Cost: \$14.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.58	0.6	0.6	\$99.00	\$14.40

<b>Total Labor Sale</b> \$99.00	<b>Total Labor Cost</b> \$14.40	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

<b>D. MISCELLANEOUS</b>	<b>DEALER STATES THAT THE FACIA BOARDS ON LEFT SIDE OF KITCHEN SLIDE OUT IS SEPERATED ON NOT FLUSH</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Poor installation or trim hooked cabinet drawer?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50  
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.03	0.3	0.3	\$49.50	\$7.20

1. Removed trim. Tightened screws on structural board. Reattached trim. requested..3 hours

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$7.20	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>E. MISCELLANEOUS</b>	<b>DEALER STATES THE CABINET FACE ON DOOR SIDE TO THE RIGHT OF SLIDE OUT NEXT TO THE ENTRY DOOR HAS A SCUFF</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scuff?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50  
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.33	0.3	0.3	\$49.50	\$7.20

1. Touched up and blended with paint marker. Undetectable now. requested.3 hours





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$7.20	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>F. MISCELLANEOUS</b>	<b>DEALER STATES THE VALANCE ABOVE THE STOVE IS HANGING LOOSE</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Missing screw on right side

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.22	0.3	0.3	\$49.50	\$7.20

1. No screw or screw hole on right side. Replaced screw. Refastened valance. Touched up with paint marker. requested .3 hours

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$7.20	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>G. MISCELLANEOUS</b>	<b>DEALER STATES THE COUCH SECTION ON DOOR SIDE HAS WHAT TO BE A STAIN FROM A PEN</b>	<b>Warranty Pay</b>	<b>\$33.00</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Pen streak





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00  
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.16	0.2	0.2	\$33.00	\$4.80

1. Attempted to remove with soap and water. Moved up to citrol. Tried again with dish soap. It looks better, but could not remove stain. Recommend new foot stool. requested .3 hours

<b>Total Labor Sale</b> \$33.00	<b>Total Labor Cost</b> \$4.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>H. MISCELLANEOUS</b>	<b>DEALER STATES THE BATHROOM SLIDING ENTRY DOOR HAS A NICK ON CORNER, CLOSE TO THE HANDLE</b>	<b>Warranty Pay</b>	<b>\$33.00</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Nick

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00  
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.2	0.2	0.2	\$33.00	\$4.80

1. Mixed grey wood putty with white until color match was achieved. Applied and smoothed wood putty. Looks good.requested.3 hours

<b>Total Labor Sale</b> \$33.00	<b>Total Labor Cost</b> \$4.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

I.	MISCELLANEOUS	DEALER STATES THE CLOSET LOCK IS NOT ATTACHED.	Warranty Pay	\$33.00
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.1	0.2	0.2	\$33.00	\$4.80

1. Unscrewed latch. Reattached handle. Refastened latch. Tested for function.requested.3 hours

<b>Total Labor Sale</b> \$33.00	<b>Total Labor Cost</b> \$4.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

J.	MISCELLANEOUS	DEALER STATES THE BOTTOM EXTRUSION UNDER DOOR SIDE NOSE CONE HAS SCRAPED OFF SEALANT	Warranty Pay	\$16.50
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Poor caulk job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$2.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.07	0.1	0.1	\$16.50	\$2.40

1. Taped area off. Applied sealant to missing area. Removed tape.requested.1 hours





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

<b>Total Labor Sale</b> \$16.50	<b>Total Labor Cost</b> \$2.40	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>K. MISCELLANEOUS</b>	<b>DEALER STATES THE OFF DOOR SIDE BOTTOM OF NOSE CONE, CORNER EXTRUSION HAS SLOPPY CUALKING</b>	<b>Warranty Pay</b>	<b>\$0.00</b>
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Sloppy caulking job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.18	0	0	\$0.00	\$0.00

1. Cleaned area off with plastic knife and dry rag.requested.2 hours

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>L. MISCELLANEOUS</b>	<b>DEALER STATES FRONT DOOR SIDE, CARGO BAY DOOR HAS A SCRATCH ON UPPER LEFT TRIM</b>	<b>Warranty Pay</b>	<b>\$0.00</b>
-------------------------	---	---------------------	---------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scratch





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.06	0	0	\$0.00	\$0.00

1. Taped off scratch for minimal area of paint not matching. Touched up with paint marker. Removed tape.requested.2 hours

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>M. MISCELLANEOUS</b>	DEALER STATES AWNING # 2 INTERIOR SWITCH DOES NOT WORK. DOES NOT SEND POWER. UNIT HAS BOTH INTERIOR AND EXTERIOR CONTROLS FOR SLIDE OUTS AND AWNINGS. EXTERIOR BOTTON OPERATES AS IT SHOULD	Warranty Pay	\$0.00
-------------------------	---	--------------	--------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Wires on spade were mixed up.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.37	0	0	\$0.00	\$0.00

1. Red and black wires to switch had to swap positions to function. Works as it should. requested 1 hour

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

N.	MISCELLANEOUS	DEALER STATES BEHIND THE MAIN DOOR HAS 3 DIFFENT SCRATCHES ON THE DECAL AND WILL NEED REPLACED	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	2.27	0	0	\$0.00	\$0.00

1. Vigorously scrubbed area with citrol and micro fiber rag Fiberglass Scratches are undeniable under light as shown in photos. Recommend body shop. requested .6 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$0.00	\$0.00

O.	MISCELLANEOUS	DEALER STATES THAT THE THE METAL BELOW THE DOOR IS ALSO SCRATCHED UP IN 2 SPOTS UNDERNEATH THE DECAL THAT HAS SCRATCHES	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scrubbed/buffed with microfiber rag. Can no longer detect scratch.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE ALPINE  
4YDFAVU2XTE760487

**Service Advisor**  
KEVIN GOODIEL  
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	1.94	0	0	\$0.00	\$0.00

1. Scratch buffed out with micro fiber rag, citrol. .1 hours

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$0.00	\$0.00	\$0.00	\$0.00

Category	Sale	Cost
Labor	\$577.50	\$84.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$577.50</b>	<b>\$84.00</b>





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
O	MISC	Fri Mar 6, 2026	7:53 AM	7:53 AM	0 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Fri Mar 6, 2026	7:53 AM	8:30 AM	0.61 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Fri Mar 6, 2026	8:30 AM	8:44 AM	0.23 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Fri Mar 6, 2026	8:44 AM	8:49 AM	0.08 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
C	MISC	Fri Mar 6, 2026	8:49 AM	8:53 AM	0.07 hrs	W	matthewl	0.6 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Fri Mar 6, 2026	8:54 AM	9:25 AM	0.51 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
D	MISC	Fri Mar 6, 2026	9:25 AM	9:27 AM	0.03 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Fri Mar 6, 2026	9:27 AM	9:32 AM	0.07 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Fri Mar 6, 2026	9:32 AM	9:45 AM	0.22 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Fri Mar 6, 2026	9:45 AM	9:45 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
G	MISC	Fri Mar 6, 2026	9:45 AM	9:55 AM	0.16 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
H	MISC	Fri Mar 6, 2026	9:55 AM	10:07 AM	0.20 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
I	MISC	Fri Mar 6, 2026	10:08 AM	10:14 AM	0.10 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
J	MISC	Fri Mar 6, 2026	10:14 AM	10:19 AM	0.07 hrs	W	matthewl	0.1 hrs
Tag: Regular Hour			Reason: -					
K	MISC	Fri Mar 6, 2026	10:20 AM	10:30 AM	0.18 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
L	MISC	Fri Mar 6, 2026	10:31 AM	10:35 AM	0.06 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
N	MISC	Fri Mar 6, 2026	10:35 AM	10:50 AM	0.25 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
N	MISC	Fri Mar 6, 2026	10:58 AM	10:58 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Fri Mar 6, 2026	10:59 AM	10:59 AM	0.01 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
M	MISC	Fri Mar 6, 2026	11:00 AM	11:22 AM	0.37 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$577.50

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM  
Ready for Pickup: Thu Mar 12, 2026 | 1:10 PM  
Promise Time: Tue Mar 10, 2026 | 7:00 PM

<b>Customer</b> linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
N	MISC	Mon Mar 9, 2026	8:04 AM	9:43 AM	1.65 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Tue Mar 10, 2026	9:56 AM	11:40 AM	1.75 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Tue Mar 10, 2026	11:40 AM	11:41 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
N	MISC	Tue Mar 10, 2026	11:44 AM	12:06 PM	0.37 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 10, 2026	12:37 PM	12:53 PM	0.26 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Tue Mar 10, 2026	12:53 PM	1:03 PM	0.18 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40236	LINK RV	\$577.50
57200	40236	LINK RV	-\$577.50
67200	40236	LINK RV	\$84.00
14400	matthewl	LINK RV	-\$84.00

