



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG14 T8920548
1 Mi In / 1 Mi Out
In Service Date:
01/01/2017
Stock #: KS26-30

Service Advisor
KEVIN GOODIEL
goodielk

| | | | | |
|----|---------------|---|--------------|---------|
| A. | MISCELLANEOUS | DEALER STATES THE WATER HEATER LATCH IS MISSING | Warranty Pay | \$39.14 |
|----|---------------|---|--------------|---------|

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 8:55 AM

1. Missing handle

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$7.20

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.28 | 0.3 | 0.3 | \$0.00 | \$7.20 |

- Ordered new door. Replaced latch
- .5 requested

Parts

Parts Total Sale Amount \$13.75

Parts Total Cost Amount \$10.58

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|--|----------|------------|------------|------------|
| 786595 - Water Heater - Door Latch - Kit ST - 525060 - Surburban - Black | 1 | \$13.75 | \$13.75 | \$10.58 |

Fees \$25.39

| Code | Description | Sale Amount | Cost Amount |
|------|-------------|-------------|-------------|
| FF | - | \$25.39 | \$0.00 |

| | | | |
|-------------------------|-------------------------|-------------------------|-------------------------|
| Total Labor Sale | Total Labor Cost | Total Parts Sale | Total Parts Cost |
| \$0.00 | \$7.20 | \$13.75 | \$10.58 |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

| | | | |
|---|---|--|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG14 T8920548 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|--|---|

| | | | |
|-------------------------|--|---------------------|----------------|
| B. MISCELLANEOUS | DEALER STATES THE DOOR SIDE MARKER LIGHT AND DOOR SIDE TAIL LIGHT ARE NOT SEALED UP ALL THE WAY | Warranty Pay | \$16.50 |
|-------------------------|--|---------------------|----------------|

Tags: Add-on

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 8:56 AM

1. Poorly applied sealant

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$7.20

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.21 | 0.3 | 0.3 | \$16.50 | \$7.20 |

1. Cleaned old sealant off of both side marker and tail light with plastic putty knife. Cleaned with dry rag. Reapplied sealant.

2. request .5 hours

| | | | |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$16.50 | Total Labor Cost \$7.20 | Total Parts Sale \$0.00 | Total Parts Cost \$0.00 |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|

| | | | |
|-------------------------|---|---------------------|----------------|
| C. MISCELLANEOUS | DEALER STATES THERE A PLUMBING VENT CAP ON THE ROOF THAT MISSING AND BROKE | Warranty Pay | \$76.36 |
|-------------------------|---|---------------------|----------------|

Tags: Add-on

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 8:57 AM

1. Missing vent cap





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

| | | | |
|---|---|--|---|
| Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG14 T8920548 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|--|---|

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$7.20

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.33 | 0.3 | 0.3 | \$49.50 | \$7.20 |

1. Ordered new vent cap. Installed and sealed.
2. .5 requested

Parts

Parts Total Sale Amount \$1.43
Parts Total Cost Amount \$1.10

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|--|----------|------------|------------|------------|
| 390798 - Caps - Vent - Plastic - Black | 1 | \$1.43 | \$1.43 | \$1.10 |

Fees \$25.43

| Code | Description | Sale Amount | Cost Amount |
|------|-------------|-------------|-------------|
| FF | Freight Fee | \$25.43 | \$0.00 |

| | | | |
|------------------|------------------|------------------|------------------|
| Total Labor Sale | Total Labor Cost | Total Parts Sale | Total Parts Cost |
| \$49.50 | \$7.20 | \$1.43 | \$1.10 |

| | | | |
|------------------|---|--------------|---------|
| D. MISCELLANEOUS | DEALER STATES THERES A 6" SMEAR ON THE REAR UPPER PANEL OF SHEET METAL ON OFF DOOR SIDE | Warranty Pay | \$82.50 |
|------------------|---|--------------|---------|

Tags: [Add-on](#)

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 8:58 AM

1. Smeard caulk





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

| | | | |
|---|---|--|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG14 T8920548 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|--|---|

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$24.00

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.33 | 0.5 | 1 | \$82.50 | \$24.00 |

- Cleaned off smeared caulk with citron and detail rag.
- .5 hours requested

| | | | |
|------------------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$82.50 | Total Labor Cost \$24.00 | Total Parts Sale \$0.00 | Total Parts Cost \$0.00 |
|------------------------------------|------------------------------------|-----------------------------------|-----------------------------------|

| | | | |
|-------------------------|--|---------------------|----------------|
| E. MISCELLANEOUS | DEALER STATES THE OFF DOOR SIDE LIGHT ABOVE THE BED FLICKERS, BATHROOM LIGHT FLICKERS, AND THE LIGHT BYE THE AC FLICKERS. 3 VIDEOS ATTACHED | Warranty Pay | \$36.07 |
|-------------------------|--|---------------------|----------------|

Tags: Add-on

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 9:00 AM

- Bad connection and bad led light in front of ac on ceiling.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$4.80

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.7 | 0.2 | 0.2 | \$33.00 | \$4.80 |

- Checked lights for flicker, function and power. Light by ac flickered. Checked and confirmed consistent power. Installed new connectors. Bathroom light and bedroom light no longer flicker. Light by ac does not work at all. I believe the the flickering was due to a weak circuit that was remedied by new connectors to ac light. Recomend new led light for ac light. CAN NOT UPLOAD VIDEOS AS REQUESTED FOR WARRANTY. PICTURES ONLY. VIDEOS WILL NOT BE IN





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

| | | | |
|---|---|--|---|
| Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222 | Billing-Customer Same as Customer | Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG14 T8920548 | Service Advisor KEVIN GOODIEL goodielk |
|---|---|--|---|

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$4.80

FILE FOLDER SEPERATELY. 2 pictures in folder 3 videos to RO.

- 2. .5 requested
- 3. Replaced light. All lights work as they should.

Parts

Parts Total Sale Amount \$3.07
Parts Total Cost Amount \$2.36

| Name | Quantity | Unit Price | Sale Price | Cost Price |
|---------------------------------------|----------|------------|------------|------------|
| 479579 - LIGHT , CEILING LED 4.50 DIA | 1 | \$3.07 | \$3.07 | \$2.36 |

| | | | |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|
| Total Labor Sale \$33.00 | Total Labor Cost \$4.80 | Total Parts Sale \$3.07 | Total Parts Cost \$2.36 |
|------------------------------------|-----------------------------------|-----------------------------------|-----------------------------------|

| | | | |
|-------------------------|---|---------------------|----------------|
| F. MISCELLANEOUS | DEALER STATES THERES HOLES IN SEALENT AROUND THE FURNACE VENT AND NEEDS TO BE SEALED | Warranty Pay | \$16.50 |
|-------------------------|---|---------------------|----------------|

Tags: [Add-on](#)

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 9:01 AM

- 1. Caulk had dripped down





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM

Ready for Pickup: Tue May 12, 2026 | 11:51 AM

Promise Time: Mon Feb 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG14 T8920548

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$2.40

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.08 | 0.1 | 0.1 | \$16.50 | \$2.40 |

1. Removed old sealant from vent. Cleaned. Applied new sealant.
2. .5 hours requested

Total Labor Sale
\$16.50

Total Labor Cost
\$2.40

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

| | | | |
|------------------|---|--------------|--------|
| G. MISCELLANEOUS | DEALER STATES IT DID NOT PASS AN LP DROP TEST ON THE STOVE AND HAS AN LP LEAK SOME WERE | Warranty Pay | \$0.00 |
|------------------|---|--------------|--------|

Tags: Add-on

Job added by KEVIN GOODIEL on Wed Feb 11, 2026 | 9:02 AM

1. ?perhaps rangetop line was cracked open?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

| Technician | Certification Number | Actual Hours | Assigned Bill Hours | Flag Hours | Labor Sale | Labor Cost |
|------------|----------------------|--------------|---------------------|------------|------------|------------|
| matthewl | - | 0.57 | 0 | 0 | \$0.00 | \$0.00 |

1. Performed drop test with rangetop twice. Passed both times. Attached 1 time photo and video. Put my phone in photo and video for proof of time stamping. Only the photo is allowed in the file. Video is attached to RO.
2. .3 hours requested





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG14 T8920548

Service Advisor
KEVIN GOODIEL
goodielk

Total Labor Sale \$0.00 Total Labor Cost \$0.00 Total Parts Sale \$0.00 Total Parts Cost \$0.00

| Category | Sale | Cost |
|----------------------|-----------------|----------------|
| Labor | \$198.00 | \$52.80 |
| Parts | \$18.25 | \$14.04 |
| Sublet | \$0.00 | \$0.00 |
| Sublet Labor | \$0.00 | \$0.00 |
| Sublet Parts | \$0.00 | \$0.00 |
| Fees | \$50.82 | \$0.00 |
| Discounts | \$0.00 | - |
| Tax | \$0.00 | - |
| Deductible | \$0.00 | - |
| Insurance/Warranty | \$0.00 | - |
| Invoice Total | \$267.07 | \$66.84 |

Clock In Info

| # | Opcode | Date | Clock In | Clock Out | Time Spent | Pay Type | Technician | Flag Hrs |
|-------------------|--------|------------------|-----------|-----------|------------|----------|------------|----------|
| A | MISC | Fri Feb 27, 2026 | 8:09 AM | 8:21 AM | 0.20 hrs | W | matthewl | 0.3 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| B | MISC | Fri Feb 27, 2026 | 8:21 AM | 8:33 AM | 0.21 hrs | W | matthewl | 0.3 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| C | MISC | Fri Feb 27, 2026 | 8:34 AM | 8:39 AM | 0.09 hrs | W | matthewl | 0.3 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| D | MISC | Fri Feb 27, 2026 | 8:39 AM | 8:58 AM | 0.33 hrs | W | matthewl | 1 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.07

RO# : 40155 Tag# : T8920548

Check-in: Wed Feb 11, 2026 | 8:55 AM
Ready for Pickup: Tue May 12, 2026 | 11:51 AM
Promise Time: Mon Feb 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG14 T8920548

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

| # | Opcode | Date | Clock In | Clock Out | Time Spent | Pay Type | Technician | Flag Hrs |
|-------------------|--------|------------------|-----------|-----------|------------|----------|------------|----------|
| E | MISC | Fri Feb 27, 2026 | 8:59 AM | 9:18 AM | 0.33 hrs | W | matthewl | 0.2 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| F | MISC | Fri Feb 27, 2026 | 9:19 AM | 9:23 AM | 0.08 hrs | W | matthewl | 0.1 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| G | MISC | Fri Feb 27, 2026 | 9:24 AM | 9:58 AM | 0.57 hrs | W | matthewl | 0 hrs |
| Tag: Regular Hour | | | Reason: - | | | | | |
| C | MISC | Mon May 11, 2026 | 3:09 PM | 3:23 PM | 0.24 hrs | W | matthewl | - |
| Tag: Regular Hour | | | Reason: - | | | | | |
| E | MISC | Mon May 11, 2026 | 3:24 PM | 3:24 PM | 0.01 hrs | W | matthewl | - |
| Tag: Regular Hour | | | Reason: - | | | | | |
| A | MISC | Mon May 11, 2026 | 3:24 PM | 3:29 PM | 0.08 hrs | W | matthewl | - |
| Tag: Regular Hour | | | Reason: - | | | | | |
| E | MISC | Mon May 11, 2026 | 3:30 PM | 3:51 PM | 0.36 hrs | W | matthewl | - |
| Tag: Regular Hour | | | Reason: - | | | | | |

