



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ALPINE
4YDFAVU2XTE760487
1 Mi In / 1 Mi Out
Stock #: KS26-33

Service Advisor
KEVIN GOODIEL
goodielk

A. MISCELLANEOUS	DEALER STATES THAT THERES LAP SEALANT ON AC ON THE ROOF, AND THERES LAP SEALANT ON TOP OF NOSE CONE	Warranty Pay	\$82.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Sloppy caulk job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.69	1	1	\$82.50	\$24.00

1. Scraped caulk off with plastic scraper on both the nose cone and ac cover. Cleaned them both off with light cleaner. requested 1 hour

Total Labor Sale \$82.50	Total Labor Cost \$24.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

B. MISCELLANEOUS	DEALER STATES THAT THE AC COVER IS NOT PUT TOGETHER CORRECTLY THE SEAMS ARE OVERLAPING EACH OTHER	Warranty Pay	\$132.00
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Hurried assembly





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00
Labor Cost: \$19.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.23	0.8	0.8	\$132.00	\$19.20

1. Ac cover was cross lapped where the 2 plastic cover pieces should join each other. Unscrewed cover, realigned. Functions as it should. Not cosmetically pleasing for a new high end unit. Recommend new cover. requested .5

Total Labor Sale \$132.00	Total Labor Cost \$19.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

C. MISCELLANEOUS	DEALER STATES DEALER STATES THAT THE OFF KITCHEN SLIDE OUT VINYL IS KINKED LIKE MAYBE THE FACIA BOARDS ARE NOT CUT SHORT ENOUGH	Warranty Pay	\$49.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Board behind trim molding was loose. Vinyl was unattached behind trim. Removed trim molding. Removed old nails. Scraped off glue. Tightened screws on backboard. Added extra screw for extra strength. Straightened and stapled vinyl to support board to fix kink in vinyl. Reattached trim. Cleaned up. requested.6 hours

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$14.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.58	0.6	0.6	\$49.50	\$14.40

1. Board behind trim molding was loose. Vinyl was unattached behind trim. Removed trim molding. Removed old nails. Scraped off glue. Tightened screws on backboard. Added extra screw for extra strength. Straightened and stapled vinyl to support board to fix kink in vinyl. Reattached trim. Cleaned up. requested.6 hours

Total Labor Sale \$49.50	Total Labor Cost \$14.40	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

D.	MISCELLANEOUS	DEALER STATES THAT THE FACIA BOARDS ON LEFT SIDE OF KITCHEN SLIDE OUT IS SEPERATED ON NOT FLUSH	Warranty Pay	\$49.50
-----------	----------------------	---	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Poor installation or trim hooked cabinet drawer?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.03	0.3	0.3	\$49.50	\$7.20

1. Removed trim. Tightened screws on structural board. Reattached trim. requested..3 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$49.50	\$7.20	\$0.00	\$0.00

E.	MISCELLANEOUS	DEALER STATES THE CABINET FACE ON DOOR SIDE TO THE RIGHT OF SLIDE OUT NEXT TO THE ENTRY DOOR HAS A SCUFF	Warranty Pay	\$33.00
-----------	----------------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scuff?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.33	0.3	0.3	\$33.00	\$7.20

1. Touched up and blended with paint marker. Undetectable now. requested.3 hours





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Total Labor Sale \$33.00	Total Labor Cost \$7.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

F. MISCELLANEOUS	DEALER STATES THE VALANCE ABOVE THE STOVE IS HANGING LOOSE	Warranty Pay	\$33.00
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Missing screw on right side

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.22	0.3	0.3	\$33.00	\$7.20

1. No screw or screw hole on right side. Replaced screw. Refastened valance. Touched up with paint marker. requested .3 hours

Total Labor Sale \$33.00	Total Labor Cost \$7.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

G. MISCELLANEOUS	DEALER STATES THE COUCH SECTION ON DOOR SIDE HAS WHAT TO BE A STAIN FROM A PEN	Warranty Pay	\$33.00
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Pen streak





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.46	0.2	0.2	\$33.00	\$4.80

1. Attempted to remove with soap and water. Moved up to citrol. Tried again with dish soap. It looks better, but could not remove stain. Recommend new foot stool. requested .3 hours
2. Googled tips on how to specifically remove pen stains. AI suggested alcohol. I scrubbed vigorously with a microfiber cloth and alcohol. Looks much better, almost undetectable.

Total Labor Sale \$33.00	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

H. MISCELLANEOUS	DEALER STATES THE BATHROOM SLIDING ENTRY DOOR HAS A NICK ON CORNER, CLOSE TO THE HANDLE	Warranty Pay	\$33.00
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Nick

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.2	0.2	0.2	\$33.00	\$4.80

1. Mixed grey wood putty with white until color match was achieved. Applied and smoothed wood putty. Looks good.requested.3 hours

Total Labor Sale \$33.00	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

I.	MISCELLANEOUS	DEALER STATES THE CLOSET LOCK IS NOT ATTACHED.	Warranty Pay	\$16.50
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.1	0.2	0.2	\$16.50	\$4.80

1. Unscrewed latch. Reattached handle. Refastened latch. Tested for function.requested.3 hours

Total Labor Sale \$16.50	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

J.	MISCELLANEOUS	DEALER STATES THE BOTTOM EXTRUSION UNDER DOOR SIDE NOSE CONE HAS SCRAPED OFF SEALANT	Warranty Pay	\$33.00
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Poor caulk job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.07	0.2	0.2	\$33.00	\$4.80

1. Taped area off. Applied sealant to missing area. Removed tape.requested.1 hours





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Total Labor Sale \$33.00	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

K. MISCELLANEOUS	DEALER STATES THE OFF DOOR SIDE BOTTOM OF NOSE CONE, CORNER EXTRUSION HAS SLOPPY CUALKING	Warranty Pay	\$33.00
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Sloppy caulking job

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.18	0.2	0.2	\$33.00	\$4.80

1. Cleaned area off with plastic knife and dry rag.requested.2 hours

Total Labor Sale \$33.00	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

L. MISCELLANEOUS	DEALER STATES FRONT DOOR SIDE, CARGO BAY DOOR HAS A SCRATCH ON UPPER LEFT TRIM	Warranty Pay	\$33.00
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scratch





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.06	0.2	0.2	\$33.00	\$4.80

1. Taped off scratch for minimal area of paint not matching. Touched up with paint marker. Removed tape.requested.2 hours

Total Labor Sale \$33.00	Total Labor Cost \$4.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

M. MISCELLANEOUS	DEALER STATES AWNING # 2 INTERIOR SWITCH DOES NOT WORK. DOES NOT SEND POWER. UNIT HAS BOTH INTERIOR AND EXTERIOR CONTROLS FOR SLIDE OUTS AND AWNINGS. EXTERIOR BOTTON OPERATES AS IT SHOULD	Warranty Pay	\$82.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Wires on spade were mixed up.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.37	0.5	0.5	\$82.50	\$12.00

1. Red and black wires to switch had to swap positions to function. Works as it should. requested 1 hour

Total Labor Sale \$82.50	Total Labor Cost \$12.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

N.	MISCELLANEOUS	DEALER STATES BEHIND THE MAIN DOOR HAS 3 DIFFENT SCRATCHES ON THE DECAL AND WILL NEED REPLACED	Warranty Pay	\$40.28
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	2.6	1	1	\$0.00	\$24.00
boiem	-	0.6	0	0	\$0.00	\$0.00

- Vigorously scrubbed area with citrol and micro fiber rag Fiberglass Scratches are undeniable under light as shown in photos. Recommend body shop. requested .6 hours
- Unpacked decal, cleaned area. Discovered wrong decal was provided. Took measurements of new and old decal. Decal needed is approximately 7 feet. Decal provided was approximately 4 feet.
- Replaced decal-MB

Parts

Parts Total Sale Amount \$14.85
Parts Total Cost Amount \$11.42

Name	Quantity	Unit Price	Sale Price	Cost Price
786528 - Diecut - 2026 - AL - Side - DC #7 - DS - Oxide Bronze	1	\$14.85	\$14.85	\$11.42

Fees \$25.43

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$25.43	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Total Labor Sale \$0.00	Total Labor Cost \$24.00	Total Parts Sale \$14.85	Total Parts Cost \$11.42
-----------------------------------	------------------------------------	------------------------------------	------------------------------------

O. MISCELLANEOUS	DEALER STATES THAT THE THE METAL BELOW THE DOOR IS ALSO SCRATCHED UP IN 2 SPOTS UNDERNEATH THE DECAL THAT HAS SCATCHES	Warranty Pay	\$330.00
------------------	--	--------------	----------

Job added by KEVIN GOODIEL on Thu Mar 5, 2026 | 4:07 PM

1. Scrubbed/buffed with microfiber rag. Can no longer detect scratch.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$330.00

Labor Cost: \$50.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	1.94	2	2.1	\$330.00	\$50.40

1. Scratch buffed out with micro fiber rag, citrol. .1 hours

Total Labor Sale \$330.00	Total Labor Cost \$50.40	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ALPINE
4YDFAVU2XTE760487

Service Advisor
KEVIN GOODIEL
goodielk

Category	Sale	Cost
Labor	\$973.50	\$194.40
Parts	\$14.85	\$11.42
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$25.43	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$1,013.78	\$205.82

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
O	MISC	Fri Mar 6, 2026	7:53 AM	7:53 AM	0 hrs	W	matthewl	2.1 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Fri Mar 6, 2026	7:53 AM	8:30 AM	0.61 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Fri Mar 6, 2026	8:30 AM	8:44 AM	0.23 hrs	W	matthewl	0.8 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Fri Mar 6, 2026	8:44 AM	8:49 AM	0.08 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
C	MISC	Fri Mar 6, 2026	8:49 AM	8:53 AM	0.07 hrs	W	matthewl	0.6 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ALPINE
4YDFAVU2XTE760487

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	Fri Mar 6, 2026	8:54 AM	9:25 AM	0.51 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
D	MISC	Fri Mar 6, 2026	9:25 AM	9:27 AM	0.03 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Fri Mar 6, 2026	9:27 AM	9:32 AM	0.07 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Fri Mar 6, 2026	9:32 AM	9:45 AM	0.22 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Fri Mar 6, 2026	9:45 AM	9:45 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
G	MISC	Fri Mar 6, 2026	9:45 AM	9:55 AM	0.16 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
H	MISC	Fri Mar 6, 2026	9:55 AM	10:07 AM	0.20 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
I	MISC	Fri Mar 6, 2026	10:08 AM	10:14 AM	0.10 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
J	MISC	Fri Mar 6, 2026	10:14 AM	10:19 AM	0.07 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
K	MISC	Fri Mar 6, 2026	10:20 AM	10:30 AM	0.18 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 KEYSTONE ALPINE 4YDFAVU2XTE760487	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
L	MISC	Fri Mar 6, 2026	10:31 AM	10:35 AM	0.06 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
N	MISC	Fri Mar 6, 2026	10:35 AM	10:50 AM	0.25 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
N	MISC	Fri Mar 6, 2026	10:58 AM	10:58 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Fri Mar 6, 2026	10:59 AM	10:59 AM	0.01 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
M	MISC	Fri Mar 6, 2026	11:00 AM	11:22 AM	0.37 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
N	MISC	Mon Mar 9, 2026	8:04 AM	9:43 AM	1.65 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Tue Mar 10, 2026	9:56 AM	11:40 AM	1.75 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
O	MISC	Tue Mar 10, 2026	11:40 AM	11:41 AM	0 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
N	MISC	Tue Mar 10, 2026	11:44 AM	12:06 PM	0.37 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 10, 2026	12:37 PM	12:53 PM	0.26 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$1,013.78

RO# : 40236 Tag# : TE760487

Check-in: Thu Mar 5, 2026 | 4:07 PM
Ready for Pickup: Tue Apr 28, 2026 | 8:39 AM
Promise Time: Tue Mar 10, 2026 | 7:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE ALPINE
4YDFAVU2XTE760487

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
O	MISC	Tue Mar 10, 2026	12:53 PM	1:03 PM	0.18 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
G	MISC	Tue Mar 31, 2026	9:21 AM	9:22 AM	0.01 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
N	MISC	Tue Mar 31, 2026	9:22 AM	9:42 AM	0.33 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
G	MISC	Tue Mar 31, 2026	9:42 AM	9:59 AM	0.29 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
N	MISC	Thu Apr 23, 2026	1:17 PM	1:53 PM	0.60 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					

