



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26989
Promised Date: 30 MAY 26



WO #: 26989 (Appointment Date: 23 APR 2026 - Time: 10:00am)

Customer: 68842 - MORROW, MIKE
Address: 1704 COOKS VALLEY ROAD
KINGSPORT, TN
37664

Home Phone: 423-292-3906

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 2025 TT FOREST RIVER NOBO
Stock Desc: NBT19.4
Model: NBT19.4
Serial #: 5NHTRDU19SD210599
Chassis #: Mileage:0
Key #: Req'n #: License #: Trim:

Purchase Date: Date In: 14 APR 26
Promise Date: 30 MAY 26
Promise Time: 09:00am
Schedule Date: Completed: Warr. Date:

Job #1 - Warranty

COMPLAINT: BEARINGS POPPING OFF WHEN DRIVING

CAUSE: DUST CAP AND BLACK HUB CENTER CAP IS DAMAGED FROM COMING OFF/LOOSE DURING TRAVEL ON BOTH SIDES OF THE UNIT

CORRECTION: REPLACE BOTH DUST CAPS AND BLACK CENTER HUBS
LABOR FOR BOTH SIDES 1.0

Subtotal for Job #1: 0.00

Job #2 - External

CS THAT THE THERMOSTAT HAS A ERROR E3 AND WAS UNABLE TO RESET

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #2: 0.00

Job #3 - External

CS THAT THE ENTRY DOOR WONT LATCH OR LOCK

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUST REQUEST A BEARING REPACK FOR THIS UNIT SINCE THE CENTER DUST CAPS AND HUBS ARE AFFECTED ON LINE 1

CAUSE: CENTER DUST CAP AND HUB CAME OFF/LOOSE FORM WHEELS AFFECTING THE BEARINGS

CORRECTION: BEARING REPACK
LABOR 1.5

Subtotal for Job #4: 0.00

Customer #: 68842
MORROW, MIKE



Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

W/O: 26989
Promised Date: 30 MAY 26

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 06 May 2026

Customer Signature : _____

Customer Work
Order



Customer #: 68842
MORROW, MIKE

