



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27204

Customer: 93904 - DAMRON, WILLIAM
Address: 112 COOK RD
MOORESBURG, TN
37811
Home Phone: 606-422-5835
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11272
Stock Desc: 2026 THTT FOREST RIVER ROGUE
32L132
Model: 32L132
Serial #: 4X4TVGH22T5404111
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 28 MAY 26
Date In: 22 MAY 26
Promise Date:
Promise Time:
Schedule Date:
Completed: 03 JUN 26
Warr. Date: 27 MAY 26

Job #1 - Warranty

COMPLAINT: DURING PREP OF UNIT TECH FOUND WATER HEATER THROWING EC AND NOT WORKING

CAUSE: TECH DIAGNOSED THE BOARD HAD POWER COMING IN AND NONE GOING OUT DURING OPERATION AND A STRONG ELECTRICAL SMELL FROM MAIN BOARD

CORRECTION: DIAGNOSE AND REPLACE WATER HEATER CONTROL BOARD
L .75

Labor

Job #	Description	Hours	Total
1	REPLACED BOARD	0.75	131.25

Parts

Part #	Description	Qty	Price	Total
F100783617	MODULE BOARD, FOR ST42 WATER HEATER SUBURBAN 521492	1.00	200.68	200.68

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	20.00	20.00

Subtotal for Job #1: 351.93

Parts Total:	200.68
Labour Total:	131.25
Sublet Total:	0.00
Extras Total:	20.00
WORK ORDER TOTAL:	351.93

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Jun 2026

W/O: 27204

Customer #: 93904
DAMRON, WILLIAM